

PRIMARY CORNER DESCRIPTION So. 1/4 Cor. for Sec. 33 only, T28-1

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by Homer D. Angell, Deputy Surveyor, under Contract #746, dated May 5, 1902 - (DCSO records Vol. 13 Page(s) 5365)

Set a basalt stone 20x16x10 ins., 15" in ground for ¼ sec. cor. marked ¼ on N. face; from which

A Fir 12" dia., bears N.14°E., 17 lks. dist. mkd. ¼ S33 BT
A Cedar 24" dia., bears S.16°W., 45 lks. dist. mkd. ¼ S4 BT.

GLO resurvey by Fred Mensch, U.S. Cadastral Engineer - under special Instructions, dated June 7, 1922 - (DCSO records Vol. 15 Page(s) 6149)

Intersect the old ¼ sec. cor. which is a basalt stone, 5x16x10 ins. above ground, firmly set, marked ¼ on N. face, and witnessed as described by the surveyor general. I change this cor. to refer to sec. 33 only, obliterate marks on the old SW. bearing tree and mark a new tree as follows:

A Fir 15" dia., bears N.14°E., 17 lks. dist. mkd. ¼ S33 BT. (Old BT)
A Fir 9" dia., bears N.30°W., 16 lks. dist. mkd. ¼ S33 BT. (New BT)

Douglas County Surveyors Office - Gary L. Langlitz; Clell E. Goodwin; M. Lenora Ladig, crew - June 4, 1975 - C.S. File 57/30-3

Found - A Stone 5"x16"x10", above ground, firmly set and mkd. with a chiseled "¼" on the N. face.

An orig. 9" Fir still 9", bears N.30°W., 10.6 ft., alive and well-healed.

An orig. 15" now 19" Fir bears N.14°E., 11.2 ft. alive and well healed.

At the corner point, We Set a 1" x 30" Iron pipe with brass cap attached, marked: County Surveyors Office 1975

T28S R1W

¼ S 33

We placed the original stone alongside the brass cap.

Douglas Co. Surveyors Office - Randall Smith and Stephen Flause, crew - June 13, 1985 - C.S. File 62/28-5

Found - 1975 DCSO brass cap on I.P., firmly set and protruding 8" above ground.

A stone, from orig. survey, mkd. ¼ on N. face, protrudes approx. 5" from ground at NE. edge of

(Cont. Next Page)

TOWNSHIP 29 RANGE 01 POINT IDENTIFIER # 372700

PRIMARY CORNER DESCRIPTION So. 1/4 Cor. for Sec. 33 only, T28-1

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

brass cap. Portion of stone exposed measures approx. 5 x 13 ins.
Orig. BT, a Fir 12" dia., now a 19" dia. 42" tall Fir stump, bears N.14°E., 11.2 ft. This tree has a well healed single blaze pointing approx. S.54°W.
Orig. BT, a Cedar 24" dia. now a 36" dia. 15" tall Cedar stump, bears S.16°W., 29.7 ft. Shows signs of 1922 obliteration of original blaze. (This is no longer a BT for the S. ¼ of S.33)
1922 BT, a Fir 9" dia., now a 9" dia. 26" tall Fir stump, bears N.30°W., 10.6 ft. Well healed single blaze.
Monument position is accepted as found.
New Accessories:
A boat spike stamped "BO 1" set in a 30" dia. 16" tall Fir stump, and bearing N.86 3/4°E., 27.0 ft.
A boat spike stamped "BO 2" set in a 31" dia. 18" tall Fir stump, and bearing N.42¼°W., 55.4 ft.
From the end of USFS Rd. #2813-607, monument bears East approx. 40 ft. dist. and slightly lower than road. Corner is in clear cut. No trees available for scribing.