

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 22 & 23

Alias	Description
_____	_____
_____	_____
_____	_____
_____	_____

GLO survey by Ernest Rands, Deputy Surveyor - Under Contract No. 790 dated Oct. 18, 1909 - (DCSO recs Vol. 14 Pg 6120)

A point on E edge of a circular pond of stagnant water 1.00 ch in dia.
Set a basalt stone 18x10x6", 12" in the ground for 1/4 sec. cor. mkd. 1/4 on W face, from which
 A fir, 18" dia., bears S.30°E., 54 lks., mkd: 1/4 S23 BT.
 A fir, 30" dia., bears S.30°W., 85 lks., mkd: 1/4 S22 BT.

Douglas Co. Surveyors Office - John Powell - Frank Jones & W. Penley - April 1969 - C.S. File 54/82-8

Found - No trace of corner stone or SW BT, corner lies in clear-cut unit.
 Orig. 18" D.Fir, now stump, S.30°E., 35.6 ft. opened for scribe.
Set - Brass cap at cor. mkd: COUNTY SURVEYORS T29S R1W
 (Steel fence post OFFICE 1/4
 alongside brass cap) 1969 S 22|S 23
New BT - 42" D.Fir S.42°E., 178.0 ft. mkd: "1/4 S23 CS BT"
Also set 3/4" I.Rod North 15.0 & 5/8" I.Rod North 25.0 ft.

Douglas Co. Surveyors Office - Randall W. Smith, Deputy - Stephen J. Flause - 4/8/2009 - C.S. File 67/28-27

Found - 2 1/2" dia., brass cap on a 1 1/2" OD iron pipe protrudes 10" out of ground. Properly marked (1969)
 18" now 18" dia., 3 ft. high burnt & rotting stump with axe marks bears S.30°E., 35.6 ft. OBT.
 3/4" IR 15 ft. north 1969
 5/8" IR 25 ft. north 1969
 1969 42" SE BT not found. We opened a 36" D.Fir that had the 1969 BT tag on E'ly trunk no scribing fd. This tree is S.43°E., 195.5 ft. from corner (1969 BT record S.42°E., 178.0 ft) I have no idea where the 1969 tree was located, no evidence of a 42" D.Fir is found at or near record.
New - 12" D.Fir double blazed & scribed "1/4 S23 CS BT" bears N.12°E., 2.0 ft.
 13" D.Fir double blazed & scribed "1/4 S22 CS BT" bears S.52°W., 3.5 ft.
 12" P.Pine double blazed & scribed "1/4 S23 CS BT" bears S.16 1/2°E., 44.5 ft.
Note - Corner lies on the east edge of small pond & 50 ft. west of a gravel road.
 Compass decl. 16 1/4°E.