

PRIMARY CORNER DESCRIPTION Sec. Cor. 10 & 11 (south) only

Alias	Description
Alias	Description
Alias	Description
Alias	Description

GLO survey by Ernest P. Rands, Deputy Surveyor - Under Contract No. 790 dated Oct. 18, 1909 - (DCSO records Vol. 14 Page(s) 6123)

-----  
Set a basalt stone 15x7x5", 10" in the ground for cor. of secs. 10, 11, 14, & 15 mkd with 4 notches on S & 2 notches on E edge, from which  
A fir, 14" dia. bears N.28°E., 18 lks mkd: T29S R1W S11 BT  
A cedar, 10" dia bears S.82°E. 32 lks mkd: T29S R1W S14 BT  
A fir, 10" dia. bears S.13°W., 13 lks mkd: T29S R1W S15 BT  
A fir, 14" dia. bears N.38°W., 21 lks mkd: T29S R1W S10 BT

GLO survey by Fred Mensch, US Cadastral Engineer - Under special instructions dated June 7, 1922 - (DCSO records Vol. 15 Page(s) 6165)

-----  
Intersect the old cor. of secs. 10, 11, 14 & 15, which is a basalt stone, 5x7x5", above ground, firmly set, marked with 4 notches on S & 2 notches on E edges, witnessed as described by the surveyor general. I obliterate marks on the NE & NW bearing trees, and change this cor. to refer to secs. 14 & 15 only, & mark 4 notches on W edge of cor.  
S.89°50'E., 1.85 chs. along the N. Bdy of sec. 14  
Set an iron post, 3 ft. long, 2" dia., 27" in the ground, for cor. of secs. 10 & 11, with brass cap mkd  
T29S R1W  
S 10 | S 11  
S 14  
1922

from which  
A fir, 10" dia., bears N.54°E., 102 lks., mkd: T29S R1W S11 BT.  
A fir, 9" dia. bears N.85°W., 42 lks. mkd: T29S R1W S10 BT

Douglas Co. Surveyors Office - John Powell - Frank Jones & W. Penley - May 27, 1969 - C.S. File 54/82-74

-----  
Found - 10" D.Fir now 30" N.54°E., 67.3' shows good scar.  
9" D.Fir now 17" N.85°W., 27.7' shows good scar.  
Brass cap at sec. cor. mkd: GENERAL LAND OFFICE 1922 properly marked.  
New BT - 16" D.Fir S.2°E., 26.2' scribed T29S R1W S14 CS BT.  
Other BTs ok & tagged.  
Note - This cor. lies 122.1 East of sec. cor. 15 & 14