

PRIMARY CORNER DESCRIPTION East 1/4 Cor. for Sec. 1 only, T29-3

Alias	Description
_____	_____
_____	_____
_____	_____
_____	_____

GLO survey by W. H. Byars, Deputy Surveyor, under Contract #376, dated Jan. 22, 1881 - (DCSO records Vol. 15 Page(s) 6323)

-----  
Set Hemlock post for ¼ sec. cor., from which  
A Fir 15" dia., bears N.30°W., 21 lks.  
A Hemlock 20" dia., bears S.40°E., 30 lks.

GLO resurvey by Elmer F. Strickler, U.S. Transitman, under Special Instructions dated Jan. 22, 1917 - (DCSO records Vol. 15 Page(s) 6231)

-----  
Intersect the old ¼ sec.cor., which is a badly decayed post standing in rock slide, marked and witnessed as described by the surveyor general. I change this cor. to refer to sec. 1 only and perpetuate it as follows: On the W. side of the old cor. is a boulder in place, 5x4x3 ft. above ground, which I mark with a cross (X) for ¼ cor. and mark ¼ W of cross; from which  
A Fir 18" dia., bears N.64°W., 30 lks. dist. mkd. ¼ S1 BT  
A Fir 18" dia., bears S.22°W., 43 lks. dist. mkd. ¼ S1 BT

BLM resurvey by James J. Carlson, Cadastral Surveyor, under Group #892, surveyed June/July 1976 - (DCSO records Vol. 39 Page(s) 15842)

-----  
Point for the ¼ sec. cor. of sec. 1 only, determined by the method of broken boundaries, falls on a sandstone boulder, 4 x 4 x 4 ft. above ground; there is no remaining evidence of the original corner.  
Seat a brass tablet, 3¼" dia., 3½" stem, in drill hole in boulder, with top mkd:  
                                          T 29 S  
                                          R 3 W R 2 W  
                                          ¼ S 1  
                                          1976  
from which a bearing object  
A sandstone boulder, 30 x 20 x 15 ft. above ground, bears N.42°W., 73 lks. dist., mkd. X BO on SE. face.  
No suitable trees available within limits.