

PRIMARY CORNER DESCRIPTION Sec. Cor. for 4, 5, 8 and 9

Alias \_\_\_\_\_ Description \_\_\_\_\_  
 Alias \_\_\_\_\_ Description \_\_\_\_\_  
 Alias \_\_\_\_\_ Description \_\_\_\_\_  
 Alias \_\_\_\_\_ Description \_\_\_\_\_

GL0 resurvey by Elmer F. Strickler, U.S. Transitman, under Special Instructions dated Jan. 22, 1917 - (DCSO records Vol. 15 Page(s) 6279)

-----  
 Set an iron post, 3 ft. long, 2" dia., 24" in the ground, for cor. of secs. 4, 5, 8 and 9, with brass cap marked

T29S R2W	
S5	S4
S8	S9
1917	

from which

- A Fir 12" dia., bears N.61°E., 28 lks. dist. mkd. T29S R2W S4 BT.
- A Fir 9" dia., bears S.74°30'E., 45 lks. dist. mkd. T29S R2W S9 BT.
- A Fir 12" dia., bears S.41°30'W., 4 lks. dist. mkd. T29S R2W S8 BT.
- A Fir 12" dia., bears N.35°W., 25 lks. dist. mkd. T29S R2W S5 BT.

BLM Rehabilitation by Timothy J. Moore, Cadastral Surveyor, under Group #1000, surveyed Oct. 26, 2000. (DCSO rec. Vol. 53 page(s) 20594-5)

-----  
 The cor. of secs. 4, 5, 8 & 9, monumented with an iron post, 2" diam., firmly set, projecting 12" above ground, with brass cap mkd.

T 29 S R 2 W	
S 5	S 4
S 8	S 9
1917	

from which the remains of the original, bearing trees

- A roothole bears N.61°E., 18.5 ft. No evidence remains of the trunk.
- A roothole bears S.74½°E., 25.7 ft., with fallen, decayed trunk, 16" diam., lying alongside, no marks visible. (Record, 29.7 ft.)
- A fir, 23" dia., bears S.41½°W., 2.6 ft., with a healed blaze.
- A fir, 21" dia., bears N.35°W., 16.5 ft., with a healed blaze.

and new bearing trees

- A fir, 13" dia. bears N.60°E. 49.3 ft. mkd. T29S R2W S4 BT
  - A fir, 20" dia. bears S.32°E. 30.6 ft. mkd. T29S R2W S9 BT
- Each new bearing tree has a 2½" x ¼" magnetic nail (MAG-NAIL) driven at the base on the right side-center.

continued next page

TOWNSHIP 29 RANGE 02 POINT IDENTIFIER # 300600

PRIMARY CORNER DESCRIPTION Sec. Cor. for 4, 5, 8 and 9

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Brent Knapp, i.e. engineering - Crew: N. Fromdahl, J. Ogden,  
and L. Heddens - 9/2022 - C.S. File 65/111-21

-----

Condition report only

Found - Brass Cap (properly mkd)  
27" Fir, S.41½°W., 2.6', healed scar  
23" Fir, N.35°W., 16.5', healed scar  
16" Fir, N.60°E., 49.3, partially open scribe  
22" Fir, S.32°E., 30.6', partially open scribe

Note - Compass decl. 15°E.