

PRIMARY CORNER DESCRIPTION S. 1/4 Cor. for Sec. 33 only

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO resurvey by Elmer F. Strickler, U.S. Transitman, under Special Instructions dated Jan. 22, 1917 - (DCSO records Vol. 15 Page(s) 6219)

Set an iron post 3 ft. long, 1" dia., 26" in the ground for 1/4 sec. cor. of sec. 33 only, with brass cap mkd: 1/4 S33
1917

from which

A Cedar 12" dia., bears N.20°30'E., 105 lks. dist. mkd. 1/4 S33 BT.

A Fir 28" dia., bears N.56°W., 73 lks. dist. mkd. 1/4 S33 BT.

Douglas Co. Surveyors Office - John M. Powell, J. Heritage & W. Penley, crew - Nov. 1968 - C.S. File 54/73-42

Found - GLO brass cap properly mkd. in 1917.
12" now 15" Cedar N.20½°E., 69.3 ft., scribe visible.

28" D.Fir now stump, N.56°W., 48.2 ft., shows good scar.

New BT - 10" Hemlock N.49°W., 34.5 ft. mkd. 1/4 S33 CS BT.

This corner lies 42.2 ft. West of 1/4 cor. Sec. 4, T30-2

Douglas Co. Surveyors Office - L.E. Monrean; P.L. Earle, J.H. Cook - Dec. 12, 1975 - C.S. File 57/39-40

Found - 1917 GLO brass cap, properly mkd. and stamped.
15" dia. Cedar bears N.22°E., 70.7 ft. (Rec. N.20½°E., 69.3 ft.) Tree has good blaze, partial scribing visible.

28" dia. Fir stump bears N.54°W., 47.8 ft. (Rec. N.56°W., 48.2 ft.) has old scar.

10" dia. Hemlock bears N.49°W., 34.5 ft. Tree is scribed "1/4 S33 CS BT".

This corner lies 43.7 ft. West of the N. 1/4 cor. Sec. 4, T30S R2W (Rec. 44.2 ft.)

BLM Dependent Resurvey by Kenneth W. Saveland, Cadastral Surveyor, under Group No. 2232, Surveyed Oct. 2008/April 2009 - (DCSO records Vol. 57 Page(s) 22646-7)

The 1/4 sec. cor. of sec. 33 only, on the N. bdy. of the Tp., perpetuated by the Douglas County Surveyor's Office in 1968, monumented with an iron post, 1" dia., firmly set, projecting 10" above ground, with brass cap (properly) mkd.

from which the remains of BTs mkd. by Strickler in 1917

continued next page

TOWNSHIP 29 RANGE 02 POINT IDENTIFIER # 340100

PRIMARY CORNER DESCRIPTION S. 1/4 Cor. for Sec. 33 only

Alias	_____	Description	_____
Alias	_____	Description	_____
Alias	_____	Description	_____
Alias	_____	Description	_____

A cedar, 21" dia., bears N.20½°E., 69.3 ft., with a healed blaze.

A sawed fir stump, 28" dia., bears N.56°W., 48.2 ft., with no marks visible.

and a BT mkd. by the Douglas County Surveyor's Office

A hemlock, 20" dia., bears N.49¾°W., 34.8 ft., with a healed blaze.

Corner is located on a broken N. slope.