

TOWNSHIP 29 RANGE 02 POINT IDENTIFIER # 440300

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 22 & 27

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO resurvey by Elmer F. Strickler, U.S. Transitman, under Special Instructions dated Jan. 22, 1917 - (DCSO records Vol. 15 Page(s) 6265)

Set an iron post, 3 ft. long, 1 in. dia., 26 ins. in the ground, for 1/4 sec. cor., with brass cap marked $\frac{1}{4}$ $\frac{S22}{S27}$
1917

from which
A Fir 24" dia., bears S.57°15'W., 25 lks. dist. mkd. $\frac{1}{4}$ S27 BT.
A Fir 20" dia., bears N.34°45'W., 118 lks. dist. mkd. $\frac{1}{4}$ S22 BT.

Douglas County Surveyors Office - Gary L. Langlitz, Deputy - Vic Cangie, crew - June 25, 1975 - C.S. File 57/30-17

Found - 1" Iron pipe, firmly set, extending 8" above ground, with brass cap attached, 1917 GLO, properly mkd. Orig. 24" now 35" D.Fir bears S.57 $\frac{1}{4}$ °W., 11.9 ft. (Rec. S.57 $\frac{1}{4}$ °W., 16.5 ft.) with scribing " $\frac{1}{4}$ " visible on a partially rotten unhealed blaze. Orig. 20" now 29" D.Fir bears N.34 3/4°W., 77.9 ft., alive and well healed.
New BT - 9" D.Fir bears S.74°E., 30.4 ft. scribed " $\frac{1}{4}$ S27 CS BT"