

TOWNSHIP 29 RANGE 02 POINT IDENTIFIER # 974010

PRIMARY CORNER DESCRIPTION Cor. No. 6 H.E.S. #140

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

Homestead Entry Survey executed by Frank D. Maxwell, Forest Service, under Special Instructions dated April 27, 1914 - (DCSO records Vol. 27 Page(s) 11744)

-----  
Cor. No. 6, 25 ft. below flat ridge, identical with Cor. H/6 of listing survey, a post, marked and witnessed as described by Asher Ireland, Asst. Forest Ranger, in place of which I Set an igneous stone, 24x8x8 ins., 14" in the ground, for Cor. 6 mkd. 6 H E S 140 on S. face, with a cross (X) on top; from which

A Cedar 10" dia., bears S.63°E., 72½ lks. dist.

A Fir 14" dia., bears N.61°50'W., 3 lks. dist.

Both trees blazed and scribed 6 H E S 140 BT.

Fd. and used in GLO resurvey by Elmer F. Strickler, U.S. Transitman, under Special Instructions dated Jan. 22, 1917 - (DCSO records Vol. 15 Page(s) 6246)

Douglas Co. Surveyors Office - Vernon "Ray" Tracy, Jack Heritage, V. Perron, crew - Nov. 18, 1969 - C.S. File 54/96-3

-----  
Found - Old corner stone, in place, mkd. "+" on top and "6 HES 140" on South.

Orig. 10" now 30" Cedar 15 ft. high snag, S.63°E., 47.9 ft. shows scar.

Orig. 14" now 25" Fir, alive, N.62°W., 2.0 ft., shows good scar. We tag.

Set Brass cap at cor. mkd: County Surveyors Office  
T 29 S R 2 W  
Cor. #6/\HES 140  
1969

Reset old corner stone alongside.

New BTs- 12" D.Fir S.46°W., 6.1 ft. mkd. 6 HES 140 CS BT.

13" Cedar N.73°E., 7.9 ft. mkd. 6 HES 140 CS BT.

This corner lies on moderate NW. slope.

Fd. OK, Sept. 22, 1981 by L. Herzstein - C.S. File 61/27-50