

TOWNSHIP 29 RANGE 02 POINT IDENTIFIER # 975030

PRIMARY CORNER DESCRIPTION Cor. No. 4 H E S #141

Alias	_____	Description	_____
Alias	_____	Description	_____
Alias	_____	Description	_____
Alias	_____	Description	_____

Homestead Entry Survey executed by Frank D. Maxwell, Forest Service, under Special Instructions dated April 27, 1914 - (DCSO records Vol. 27 Page(s) 11751)

-----

Cor. No. 4, identical with Cor. H/10 of listing survey, a hollow stump, mkd. and witnessed as described by the listing surveyor; in place of which (after removing shell of stump), I Set an igneous stone 24x12x6 ins., 14" in the gorund, for Cor. No. 4, chiseled 4 H E S 141 on NE. face, with a cross (X) on top; from which

A Fir 24" dia., bears S.6°15'W., 14 lks. dist.

A Fir 20" dia., bears N.60°00'W., 36 lks. dist.

Both trees blazed and scribed 4 H E S 141 BT.

Douglas Co. Surveyors Office - VRT & Crew - Nov. 1969 - C.S. File 54/96-12

-----

Looked for, not found. Possible O.B.T. stump, showed scar, rotted out, no scribe found. Cor. would fall on cut ank of new access road. Other OBT would fall in approx. ditch lines of Road.

Harold L. Center, for Umpqua National Forest, Aug. 1995 M122-66; CS 63/151-2

-----

Set 2½" dia. iron post with a 2½" dia. brass cap monument attached and marked: "T29S R2W HES 141 Cor 4 1995 LS 1071"

New Accessories -

7" dia. Fir, bears S.15°46'W., 19.32 ft. scribed "COR 4 HES 141 LS1071 BT"

10" Dia. Fir, bears N.82°10'W., 45.80 ft. scribed "X BT"

2½" dia. brass cap monument set flush with the ground bears N.71°46'38"E., 424.59 ft. distance, cap marked: "USFS GPS HES No. 141 1995 LS 2332"