

TOWNSHIP 29 RANGE 02 POINT IDENTIFIER # 975040

PRIMARY CORNER DESCRIPTION Cor. No. 5 H.E.S. #141

| | | | |
|-------|-------|-------------|-------|
| Alias | _____ | Description | _____ |
| Alias | _____ | Description | _____ |
| Alias | _____ | Description | _____ |
| Alias | _____ | Description | _____ |

Homestead Entry Survey executed by Frank D. Maxwell, Forest Service, under Special Instructions dated April 27, 1914 - (DCSO records Vol. 27 Page(s) 11751)

Cor. No. 5, identical with Cor. H/9 of listing survey, a post, mkd. and witnessed as described by the listing surveyor, in place of which I
Set a wash boulder 24x12x6 ins., 14" in the ground, for Cor. 5, mkd. 5 H E S 141 on NE. face, with a cross (X) on top; from which

A Fir 24" dia., bears S.15°45'W., 15 lks. dist.

A Fir 26" dia., bears N.69°30'W., 9½ lks. dist.

Both trees blazed and scribed 5 H E S 141 BT.

Douglas Co. Surveyors Office - VRT & Crew - Nov. 1969 - C.S. File 54/96-12

Looked for, not found. Corner and OBTs would fall in slide removal area on S. side new access road.

Harold L. Center, for Umpqua National Forest, Aug. 1995 M122-66; CS 63/151-2

Set 2½" dia. iron post with a 2½" dia. brass cap monument attached and marked: "T29S R2W HES 141 Cor 5 1995 LS 1071"
New Accessories -

5" dia. Fir, bears S.59°39'E., 17.37 ft. scribed "X BT"

10" dia. Fir, bears N.11°23'W., 73.56 ft. scribed "Cor 5 HES 141 LS1071 BT"