

PRIMARY CORNER DESCRIPTION Cor. No. 7 H.E.S. #141

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

Homestead Entry Survey executed by Frank D. Maxwell, Forest Service, under Special Instructions dated April 27, 1914 - (DCSO records Vol. 27 Page(s) 11752)

Cor. No. 7, identical with Cor. H/7 of listing survey, a post, mkd. and witnessed as described by the listing surveyor; in place of which I
Set an igneous stone 24x12x10 ins., 14" in the ground for Cor. 7, mkd. 7 H E S 141 on SE. face, with a cross (X) on top. from which
A Fir 28" dia., bears N.44°45'E., 84 lks. dist.
A Fir 8" dia., bears N.78°30'W., 6½ lks. dist.
Both trees blazed and scribed 7 H E S 141 BT.

Douglas Co. Surveyors Office - Vernon "Ray" Tracy, Jack Heritage, V Perron, crew - Nov. 20, 1969 - C.S. File 54/96-11

Found - Old corner stone, in place, broken, mkd. "+" on top and "7 HES 141" on S. side.
Orig. 28" now 30" Fir, dead snag, N.44 3/4°E., 55.4 ft., scribe visible on unhealed blaze.
Orig. 8" now 18" Fir, alive, N.78½°W., 4.3 ft., shows good scar.
Set Brass cap at cor. mkd: County Surveyors Office
T 29 S R 2 W
Cor. #7 /HES 141
1969
Reset stone alongside.
New BT - 36" Cedar N.34°E., 31.0 ft. mkd. "7 HES 141 CS BT"
This corner lies on N. side of roadway into claim at top of cut bank.

Leonard Herzstein, U.S.F.S. (Deputized by the County) Wit: J. Landrum; T. Wolford - May 19, 1981 - C.S. File 61/24-28

Found - 1" I.P., firmly set, projecting 10" above 3 ft. mound of stone with brass cap mkd. in 1969.
Orig. 30" D.Fir stob bears N.44 3/4°E., 55.4 ft. with no marks visible.
Orig. 16" D.Fir snag bears N.78½°W., 4.3 ft. with healed blaze and rescribed by Tracy in 1969 7 HES 141 CS BT visible on partly healed blaze.
1969 BT, 36" I.Cedar bears N.34°E., 31.4 ft. (Rec. 31.0 ft.) with scribe marks 7 HES 141 CS BT visible on partly healed blaze.
New BT - 14" Maple bears N.31°W., 16.7 ft. scribed "7 HES 141 CS BT" on double blaze.