

PRIMARY CORNER DESCRIPTION Cor. #11 H E S #141

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

Homestead Entry Survey executed by Frank D. Maxwell, Forest Service, under Special Instructions dated April 27, 1914 - (DCSO records Vol. 27 Page(s) 11754)

Cor. No. 11, identical with Cor. H/4 of listing survey, an Ash tree, 18" dia., mkd. and witnessed as described the listing surveyor.
I blaze and scribe the tree "11 H E S 141" on SW. face, for Cor. 11; from which
 A Fir 26" dia., bears N.9°15'E., 48 lks. dist.
 A Fir 6" dia., bears N.67°45'E., 31 lks. dist.
Both trees blazed and scribed 11 H E S 141 BT.

Douglas Co. Surveyors Office - Vernon "Ray" Tracy, Jack Heritage, V Perron, crew - Nov. 21, 1969 - C.S. File 54/96-18

Found - Stump of orig. 18" now 20" Ash corner tree, opened on S. side, scribe visible.
 Orig. 26" now 32" Fir, alive, N.9¼°E., 31.7 ft. shows very good scar. Tag.
 Orig. 6" now 14" W.Fir, alive, N.67 34/°E., 20.5 ft., faint scar. We rescribe "11 HES 141 CS BT"
Set at a point 1.2 ft. South of center of corner tree:
Set Brass cap at cor. mkd: County Surveyors Office
 T 29 S R 2 W
 Cor. #11 HES 141
 1969
This corner lies at bottom of hill about 20 ft. North of Deadman Creek.

Survey by James Artman, LS #2268 - For: U.S. Forest Service -Nov. 1990 - C.S. File 63/104-68

Found - 1" Iron pipe with 2½" brass cap 12" above ground set on the SW. side of an Ash stump.
 20" Ash stump, original corner tree.
 36" D.Fir bears N.9°15'E., 31.7 ft. with healed blaze.
 14" W.Fir, down and rotted, bears N.67°45'E., 20.5 ft.
Set 5/8" x 30" Iron rod with a 1" yellow plastic cap 27" in the ground, mkd. "ARTMAN RLS 2268" for reference monument, bears S.58°30'E., 20.0 ft.
Painted corner tree and tagged all BTs. Set 6 ft. alum. post alongside rod with 54-2, 54-9, and 54-3 signs attached.