

TOWNSHIP 29 RANGE 02 POINT IDENTIFIER # 975130

PRIMARY CORNER DESCRIPTION Cor. #1 H.E.S. #141

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

Homestead Entry Survey executed by Frank D. Maxwell, Forest Service, under Special Instructions dated April 27, 1914 - (DCSO records Vol. 27 Page(s) 11749-50)

-----  
Cor. No. 1, identical with Cor. H/1 of listing survey No. 6-490, a Fir tree 30" dia., mkd. and witnessed as described by the listing surveyor.

I Blaze and scribe the tree "1 H E S 141" on NW. face for cor.; from which

A Fir 16" dia., bears S.55°30'W., 11 lks. dist.

A Fir 12" dia., bears N.8°10'W., 39 lks. dist.

Both trees blazed and scribed 1 H E S 141 BT.

The Forest Service monument, a large boulder in Deadman Creek, mkd. and witnessed as described by the listing surveyor, bears S.46°21'W., 6.66 chs. I destroy markings on trees and boulder.

Douglas Co. Surveyors Office - Vernon "Ray" Tracy, Jack Heritage, V. Perron, crew - Nov. 19, 1969 - C.S. File 54/96-8

-----  
Found - Orig. 30" now 36" Fir corner tree, alive, shows good scar on NW. side.

Orig. 16" now 18" Fir, alive, S.55½°W., 7.3 ft., shows very good scar. We tag.

Orig. 12" now 15" Fir, alive, N.8°W., 25.7 ft., shows good scar. We tag.

At base of corner tree, 18" due West of center, SET

Brass cap at cor. mkd. County Surveyors Office

T 29 S R 2 W

Cor. #1\_\_\_\_\HES 141

1969

This corner lies on steep westerly slope about 155 ft. E. of Deadman Creek.