

PRIMARY CORNER DESCRIPTION Sec Cor for 6 & 7 only, W. Bdy

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Original - Nathaniel Ford, under Contract #44 dated May 30, 1854 - (DCSO records Vol. 15 Page(s) 6297)

Set a post cor. of secs. 1, 6, 7 and 12, from which

- A Maple 10" dia., bears S.57°E., 35 lks. dist.
- A Red Fir 10" dia., bears N.40°E., 35 lks. dist.
- A Cedar 40" dia., bears S.40°W., 9 lks. dist.
- A Red Fir 12" dia., bears N.50°W., 20 lks. dist.

GLO resurvey by W.H. Byars, Contract #376, dated Jan. 22, 1881, found all bearing trees standing. (DCSO records, Vol. 15 Page 6315)

Douglas Co. Surveyors Office - James Byron, Deputy - Mike Darby; Wm. S. Stoffel crew - Nov. 1962 - C.S. File 52/126-81

Found - Orig. 10" now 30" R.Fir N.40°E., 30.0 ft., not 23.1 ft., previously opened, shows good scribing.
 Orig. 40" now 44" Cedar snag, shell only, S.40°W., 5.9 ft., no scribing.

Set Brass cap at cor. mkd: County Surveyors Office

	T	29	S	
R			S 6	R
4			S 7	3
W	1962			W

New BT - 6" Hemlock bears S.20°E., 6.6 ft. scribed S7 CS BT.

BLM resurvey by Donald Beck, Cadastral Surveyor, under Group #554 - Surveyed July 1964/April 1965 - (DCSO records Vol. 33 Page(s) 13796)

The cor. of secs. 6 and 7 only, remonumented and recorded by Byron in 1962, with an iron post 1" dia., 18" above ground, firmly set, with properly mkd. brass cap from which the remains of the original bearing trees:

- A Fir 30" dia., bears N.40°E., 46 lks. dist., mkd. 2 on opened blaze. (Rec. 35 lks.)
- A Cedar snag 44" dia., bears S.40°W., 12 lks. dist. 9 lks. dist. to face, no marks remaining. (Rec. 9 lks.)
- A stump hole bears N.50°W., 20 lks. dist.

and a bearing tree mkd. by Byron:

- A Cedar 8" dia., bears S.22 3/4°E., 10 lks. dist. mkd. S7 CS BT on double blaze.

Add the marks BLM to the brass cap.

(Cont. Next Page)

TOWNSHIP 29 RANGE 03 POINT IDENTIFIER # 100600

PRIMARY CORNER DESCRIPTION Sec cor for 6 & 7 only, W. Bdy.

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

BLM resurvey by James E. Jelley and Wayne L. Rogers, Cadastral Surveyors, under Group #997, surveyed Oct. 1979/April 1980 (DCSO records Vol. 43 Page(s) 16900-01)

The cor. of secs. 6 and 7, determined at record bearing and distance from the remains of an original bearing tree

A Fir stump 30" dia., bears N.40°E., 46 lks. dist. with scribe mark 2 visible on opened blaze.

At the corner point

Set an iron post, 28" long, 2 1/2" dia., 24" in the ground, with brass cap mkd:

T 29 S	T 29 S
R 4 W	S 6
S 1	S 7
	R 3 W

1980

from which new bearing trees

A Grand Fir 8" dia., bears N.31 3/4°E., 102 lks. dist. mkd. T29S R3W S6 BT.

A Grand Fir 9" dia., bears S.29½°E., 58 lks. dist. mkd. T29S R3W S7 BT.

BLM Dependent resurvey by A Bert Skeesick Cadastral Surveyor, under Group No. 2300: Admin. file #0602, surveyed May/June 2006 - (DCSO recs Vol. 56 Pg 22315 & Plat T29-4 2011-2)

The cor. of secs. 6 & 7, T29-3 on the E bdy. of the Tp. remonumented by Jelley & Rogers in 1979-80, monumented with an iron post, 2½" dia., firmly set, projecting 7" above ground, with brass cap (properly) mkd.

from which the remains of an orig. BT

A sawed fir stump, 30" dia., bears N.40°E., 30.4 ft. with no marks visible.

and BTs mkd. by Jelley and Rogers

A fir, 19" dia., bears N.31¾°E., 67.3 ft. with a healed blaze.

A fir, 23" dia., bears S.29½°E., 38.3 ft. with a healed blaze.