

TOWNSHIP 29 RANGE 03 POINT IDENTIFIER # 100640

PRIMARY CORNER DESCRIPTION W. 1/4 Cor. for Sec. 6 only

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Original - Nathaniel Ford, under Contract #44 dated May 30, 1854 - (DCSO records Vol. 15 Page(s) 6297)

-----  
Set ¼ sec. post, from which  
A Laurel 4" dia., bears S.45°W., 44 lks.  
A Laurel 4" dia., bears N.20°E., 10 lks.

GL0 survey by W. H. Byars, Deputy Surveyor, under Contract #376, dated Jan. 22, 1881 - (DCSO records Vol. 15 Page(s) 6315)

-----  
Unable to find old post or witness trees. Set new post, A Fir for ¼ sec. cor., from which  
A Fir 18" dia., bears S.40°E., 26 lks.  
A Fir 22" dia., bears S.45°W., 19 lks.

John H. Markham, Jr. - Oct. 17, 1962 - C.S. File 42/315-9

-----  
As determined by old bearing trees:  
20" Fir S.40°E., 17.2 ft., found scribe.  
31" Fir S.45°W., 17.2 ft., found scribe.  
At corner point, SET 1½" x 30" truck axle, from which  
20" Fir bears N.56°W., 34.6 ft. mkd. ¼ S6 BT.  
40" Fir bears S.65°E., 30.6 ft. mkd. bark scribed "¼ S6 BT T29S R3W".  
Rock road bears West, 80.0 ft.

BLM resurvey by Donald Beck, Cadastral Surveyor, under Group #554 - Surveyed July 1964/April 1965 - (DCSO records Vol. 33 Page(s) 13797)

-----  
The ¼ sec. cor. of 6 only, perpetuated and recorded by Markham, in 1962, with a truck axle, 1½" dia., 6" above ground, firmly set, from which the remains of the original bearing trees:

A Fir 26" dia., bears S.35½°E., 26 lks. dist. mkd. ¼ S BT on bark blaze. (Rec. S.40°E.)

A sawed Fir stump 38" dia., bears S.48 ¾°W., 26 lks. dist. with illegible scribe marks visible. (Rec. S.45°W., 19 lks.)

and bearing trees mkd. by Markham:

A Fir 20" dia., bears N.57°E., 52 lks. dist. mkd. ¼ S6 BT on double blaze.

A Fir 40" dia., bears S.64°E., 45 lks. dist., mkd. BT ¼ S6 T29S R3W on bark blaze.

At the corner point

(Cont. Next Page)

TOWNSHIP 29 RANGE 03 POINT IDENTIFIER # 100640

PRIMARY CORNER DESCRIPTION W. 1/4 Cor. Sec. 6 only

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Set an iron post, 28" long, 2 1/2" dia., 22" in the ground, with brass cap mkd:

1/4 T 29 S  
R 3 W  
S 6

1964

Reset truck axle alongside the iron post.

BLM Dependent resurvey by A Bert Skeesick Cadastral Surveyor, under Group No. 2300: Admin. file #0602, surveyed May/June 2006 - (DCS0 recs Vol. 56 Pg 22315 & Plat T29-4 2011-2)

-----  
The 1/4 sec. cor. of sec. 6 only, T29-3 remonumented by Beck in 1964-65, monumented with an iron post, 2 1/2" dia., firmly set, projecting 6" above ground, with brass cap (properly) mkd. from which the remains of the orig. BTs

A sawed fir stump, 26" dia., bears S.35 1/2°E., 17.2 ft. with scribe marks 1/4 S / BT visible in the bark.

A sawed fir stump, 40" dia., bears S.48 3/4°W., 17.2 ft. with axe marks visible.

and BT mkd. by Markham in 1962, reported by Beck

A decayed fir stump, 21" dia., bears N.57°E., 34.3 ft. with no marks visible.

A sawed fir stump, 50" dia., bears S.64°E., 29.7 ft. with fragmentary scribe marks visible in the bark.

and new BTs

A fir, 10" dia., bears N.54°E., 5.5 ft., mkd: 1/4 S6 BT.

A fir, 7" dia., bears S.12°E., 18.3 ft., mkd: 1/4 S6 BT.

Each new bearing tree has a 2 1/2"x 1/4" magnetic nail (Mag Nail) driven at the base right side-center.

The geodetic position shown hereon was determined by differentially corrected carrier phase GPS receivers relative to the National Spatial Reference System

Latitude 43°04'44.03"N Longitude 123°07'00.01"W  
(NAD 1983 (CORS 96))