

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 30 and 31

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by Dennis Hathorn, Deputy Surveyor under Contract #73, dated June 8, 1857 - (DCSO records Vol. 15 Page(s) 6310)

Set ¼ sec. post, from which
 Fir 40" dia., bears S.15°W., 20 lks. dist.
 A Fir 40" dia., bears N.57°W., 30 lks. dist.

Douglas Co. Surveyors Office - Gary Langlitz; Frank C. Silagy
July 18, 1978 - C.S. File 60/11-28

Found the only remaining bearing tree, an orig. 40" D.Fir, now a 42" windfall with illegible scribe marks visible on the bark on a burnt blaze located on the underside of the tree. This tree bears N.57°W., 19.8 ft. from the corner point. At the corner point, We set a 1" x 30" I.P., 27" in the ground with brass cap attached mkd. Douglas County Surveyor

T 29 S R 3 W
 ¼ $\frac{S\ 30}{S\ 31}$
 1978

We mark the following BTs:
 24" I.Cedar with old location poster and various cruiser's marks, bears S.38°W., 10.0 ft. scribed "¼ S31 CS BT" on a double blaze.
 14" G.Fir scribed "¼ S3 CS BT" on a double blaze, bears N.78°E., 31.9 ft.
Corner located approx. 50 ft. North of an easterly flowing creek and approx. 300 ft. West of a creek, course South.

James Klein - For: Williams/Pacific Connector Gas Pipeline Project - 7/2015 - M166-44 A-F

Found - 2½" brass cap stamped Douglas County Surveyor 1978
 36" cedar with healed face and old tag dated 6/48, S.38°W., 10.0'
New - 13" fir (scribed ¼ S30 BT), tag dated 11/13, N.45°E., 17.2' to nail side center.