

PRIMARY CORNER DESCRIPTION Sec Cor for 7, 8, 17 and 18

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by Dennis Hathorn, Deputy Surveyor under Contract #73, dated June 8, 1857 - (DCSO records Vol. 15 Page(s) 6314)

Set post cor. secs. 7, 8, 17 and 18, from which
A Laurel 18" dia., bears N.12°E., 27 lks.
A Laurel 10" dia., bears S.30°E., 28 lks.
A Laurel 12" dia., bears N.22°W., 62 lks.
A Laurel 10" dia., bears SW., 2 lks. (Per Byars 1881 report, this BT is S.45°W.)

Fd. and used in GLO survey by W. H. Byars, Deputy Surveyor, under Contract #376, dated Jan. 22, 1881 - (DCSO records Vol. 15 Page(s) 6347)

Douglas Co. Surveyors Office - James Byron, Deputy - Mike Darby; Wm. Stoffel, crew -Nov. 1962 - C.S. File 52/126-78

Found - Orig. BT, 18" Laurel N.12°E., 27 lks. scribing on tree, tree now 27", 18.4 ft.

Set Brass cap at cor. mkd: County Surveyors Office
T 29 S R 3 W
S 7 | S 8
S18 | S17
1962

New BTs- 8" Hemlock S.25°E., 12.8 ft. scribed T29S R3W S17 CS BT.
13" D.Fir N.27°W., 38.4 ft. scribed T29S R3W S7 CSBT
12" Cedar S.87°W., 67.8 ft. scribed T29S R3W S18 CS BT.

Fd. and used in BLM resurvey by James E. Jelley and Wayne L. Rogers, Cadastral Surveyors, under Group #997, surveyed Oct 1979/April 1980 (DCSO records Vol. 43 Page(s) 16896-97)

BLM resurvey by Dale T. Bedell, Cadastral Surveyor, under Group #1503, surveyed Sept. 1989/April 1990 - (DCSO records Vol. 50 Page(s) 18959-60)

(Corner Report)
The Sec. cor., monumented with an iron post 1½" dia., firmly set, projecting 12" above ground with brass cap mkd. in 1962, from which an original bearing tree
A Madrone 30" dia., bears N.12°E., 27 lks. dist., with illegible scribe marks on partially healed blaze. (Rec. N.6°E.)
and bearing trees mkd. by Byron in 1962
(Cont. Next Page)

TOWNSHIP 29 RANGE 03 POINT IDENTIFIER # 200500

PRIMARY CORNER DESCRIPTION Sec Cor for 7, 8, 17 and 18

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

A Fir 16" dia., bears S.33°E., 19½ lks. dist, with healed blaze.
A Cedar 22" dia., bears S.80°W., 100 lks. dist., with healed blaze. (Rec. 105 lks.)
A Fir 20" dia., bears N.34°W., 58 lks. dist., with healed blaze.

Fd. OK, July 1990 - M 110-40