

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 28 and 29

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by Dennis Hathorn, Deputy Surveyor under Contract #73, dated June 8, 1857 - (DCSO records Vol. 15 Page(s) 6305)

Set ¼ sec. post, from which
 A Laurel 12" dia., bears N.50°E., 21 lks.
 A Laurel 12" dia., bears N.14°W., 50 lks.

Survey by Robert M. Thompson - July 1, 1956 - C.S. File 42/178

Found no trace of original corner.
I reset corner on true sec. line at mid-point between section corners. Set a 3/4" Iron pipe, from which I scribe two new trees:
 12" Madrone S.63°40'E., 1.6 ft.
 15" W.Fir N.69°50'W., 42.3 ft.

Douglas Co. Surveyors Office - James Byron, Deputy - John Powell; Wm. Stoffel, crew - Oct. 1962 - C.S. File 52/126-68

Found Pipe and both BTs as recorded by Thompson. Laurel to SE. now down and pipe out of ground.
Reset 3/4" I.P. at corner and scribe new BT:
 9" Cedar bears N.67°E., 16.0 ft. scribed ¼ S28 CS BT.

Survey by Bruce Shaner, PLS #430 - For: Longview Fibre - Aug. 10, 1979 - M 70-80

Found - 3/4" Iron pipe.
 20" W.Fir, face overgrown, bears N.70°W., 43.5 ft. (Rec. 42.3 ft.)
 11" Cedar scribes visible, bears N.67°E., 16.0 ft.
 18" Madrone, blowdown, scribes visible, bears S.64°E., 1.6 ft.
Set Brass cap mkd. T29S R3W W.M. 1/4S S29 S30 1979 PLS 430.
Reset found 3/4" Iron pipe alongside brass cap.

FD. BC & BT - Set 6' steel post 2' East by D. Edwards, 1/2007 - M152-14