

PRIMARY CORNER DESCRIPTION Sec. Cor. for 16, 17, 20 and 21

Alias	Description
_____	_____
_____	_____
_____	_____
_____	_____

GLO survey by Dennis Hathorn, Deputy Surveyor under Contract #73, dated June 8, 1857 - (DCSO records Vol. 15 Page(s) 6306)

-
- Set post cor. secs. 16, 17, 20 and 21, from which
- A Fir 24" dia., bears N.50°E., 31 lks.
 - A Fir 36" dia., bears S.5°E., 19 lks.
 - A Laurel 12" dia., bears S.75°W., 38 lks.
 - A Laurel 18" dia., bears N.10°W., 181 lks.

BLM resurvey by James E. Jelley and Wayne L. Rogers, Cadastral Surveyors, under Group #997, surveyed Oct 1979/April 1980 (DCSO records Vol. 43 Page(s) 16884)

Point for the cor. of secs. 16, 17, 20 and 21, at proportionate distance; there is no remaining evidence of the original corner.

Set an iron post 28" long, 2½" dia., 24" in the ground, with brass cap mkd. T 29 S R 3 W

S 17 S 16
S 20 S 21
1980

from which bearing trees and a reference monument

- A Fir 18" dia., bears N.10½°E., 172 lks. dist., mkd. T29S R3W S16 BT.
- A Cedar 18" dia., bears S.4°E., 278 lks. dist., mkd. T29S R3W S21 BT.
- An Iron post 28" long, 2½" dia., set 24" in the ground, for a reference monument, bears S.50°W., 35 lks. dist., with brass cap mkd. T29S R3W S20 RM 1980 and an arrow pointing to the corner.
- A Pine 16" dia., bears N.63½°W., 165 lks. dist., mkd. T29S R3W S17 BT.