

TOWNSHIP 29 RANGE 03 POINT IDENTIFIER # 300440

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 16 and 17

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GL0 survey by Dennis Hathorn, Deputy Surveyor under Contract #73, dated June 8, 1857 - (DCSO records Vol. 15 Page(s) 6307)

-----  
Set ¼ sec. post, from which  
A Pine 30" dia., bears N.36°E., 75 lks.  
An Oak 10" dia., bears N.15°W., 150 lks.

BLM resurvey by James E. Jelley and Wayne L. Rogers, Cadastral Surveyors, under Group #997, surveyed Oct 1979/April 1980 (DCSO records Vol. 43 Page(s) 16885)

-----  
Point for the ¼ sec. cor., at proportionate distance; there is no remaining evidence of the original corner.  
Set an iron post, 28" long, 2 1/2" dia., 24" in the ground, with brass cap mkd:  
T 29 S R 3 W  
1/4  
S 17 | S 16  
1980

from which  
A Pine 18" dia., bears N.25½°E., 211 lks. dist., mkd. ¼ S16 BT.  
A Fir 22" dia., bears S.86°W., 71½ lks. dist., mkd. ¼ S17 BT.

Fd. and used in BLM resurvey by Dale T. Bedell, Cadastral Surveyor, under Group #1503, surveyed Sept. 1989/April 1990 - (DCSO records Vol. 50 Page(s) 18962)

Fd. OK by R. Brown, May 2000 - M132-40

BLM survey by Scott Toldness - PLS 90216 - Glahe & Associates Professional Land Surveyors - 2024 - M185-29 A/D

-----  
Found - All ok per record.  
Set - 8" Fir bears N.57½°W. 116.3' to a nail scribed "¼S17BT"  
9" Pine bears N.35°W. 113.15' to a nail scribed "¼S17BT"  
New - Added paint, snow blazes, nails right side center, and LS washer 90216 to BTs. No suitable trees to the East.