

TOWNSHIP 29 RANGE 03 POINT IDENTIFIER # 340200

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 28 and 33

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO survey by Dennis Hathorn, Deputy Surveyor under Contract #73, dated June 8, 1857 - (DCSO records Vol. 15 Page(s) 6302)

-----  
A Cedar 6" dia., ¼ sec. post, from which  
A Fir 15" dia., bears S.70°E., 12 lks. dist.  
A Fir 12" dia., bears N.75°W., 10 lks. dist.

Fd. and used in GLO survey by W. H. Byars, Deputy Surveyor, under Contract #376, dated Jan. 22, 1881 - (DCSO records Vol. 15 Page(s) 6340)

Ben B. Irving, County Surveyor - N.E. Richardson; Loren Weber - May 27, 1941 - C.S. File 16/55

-----  
This corner is as described in the original government field notes. The Cedar corner tree is dead but excellently preserved. Drove a ½" x 48" Iron pipe at the base of the corner tree and remarked both original bearing trees.

Douglas Co. Surveyors Office - James Byron, Deputy - Milo Godfrey; S.A. Bilow, crew - Feb. 19, 1959 - C.S. File 49/47-7

-----  
Found - Orig. 6" now 6" Cedar snag corner tree scribed "¼S ¼S" with 1/2" pipe at base.  
Orig. 15" now 32" Fir stump, S.70°E., 8.0 ft., shows bark scribing and old scars.  
Stump hole checks bearing and distance for orig. NW BT.  
New BTs- 13" R.Fir bears S.32°W., 27.5 ft. scribed ¼ S33 CS BT.  
12" R.Fir bears N.8°W., 53.7 ft. scribed ¼ S28 CSBT

BLM Resurvey by James E. Jelley and Lynn Roseberry Cadastral Surveyors under Group #554 - Surveyed May 1966/Oct. 1967 - (DCSO records Vol. 34 Page(s) 14042-43)

-----  
The ¼ sec. cor., determined in the center of the stump hole of the original corner tree, an uprooted Cedar lying alongside 6" dia., with scribe marks ¼ S visible on N. and ¼S. visible on S. side on partially healed blazes, from which the original bearing trees:

A Fir root crown size indeterminate, bears N.75°W., 10 lks. dist., with no marks remaining.  
A sawed Fir stump 32" dia., bears S.70°E., 12 lks. dist., with illegible scribe marks visible on remaining portion of opened blaze.  
and bearing trees mkd. by Byron in 1959  
(Cont. Next Page)

TOWNSHIP 29 RANGE 03 POINT IDENTIFIER # 340200

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 28 and 33

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

A Fir 15" dia., bears N.9°W., 82 lks. dist., with a healed blaze.  
A Fir 15" dia., bears S.28¼°W., 42 lks. dist, with a healed double blaze.  
At the corner point  
Set an iron post, 28" long, 2 1/2" dia., 24" in the ground, with brass cap mkd:  
T 29 S R 3 W  
¼ S 28  
S 33  
1967

FD. BC & 2 BTs - by D. Edwards, 1/2007 - M152-14