

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 16 and 21

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

GLO survey by Dennis Hathorn, Deputy Surveyor under Contract #73, dated June 8, 1857 - (DCSO records Vol. 15 Page(s) 6306)

-----  
An Alder 5" dia., ¼ sec. cor., from which  
A Fir 24" dia., bears N.30°E., 23 lks.  
An Alder 6" dia., bears S.50°W., 15 lks.

June 22, 1900 - Present, Jas. Newton; Cloyd Chaney; C.Sellers (No other info. recorded in Ren. #1, former cor. records - surveyor or source)

-----  
Set a Vinemaple post, from which  
An Alder 18" dia., bears N.11½°E., 15 lks. dist.  
A Cherry 6" dia., bears S.36°W., 13 lks. dist.  
The SW. BT is entirely destroyed. The NE. BT is fallen down but with plain marks.

BLM resurvey by James E. Jelley and Wayne L. Rogers, Cadastral Surveyors, under Group #997, surveyed Oct 1979/April 1980 (DCSO records Vol. 43 Page(s) 16885)

-----  
Point for the ¼ sec. cor., at proportionate distance; there is no remaining evidence of the original corner.  
Set a brass tablet, 3 1/2" dia., 3¼" stem, in bedrock, with top mkd. T 29 S R 3 W  
1/4  $\frac{S\ 16}{S\ 21}$   
1980  
from which  
A Fir 12" dia., bears N.85¼°E., 110 lks. dist., mkd. ¼ S16 BT.  
A Cedar 25" dia., bears S.81½°W., 75 lks. dist., mkd. ¼ S21 BT.

Fd. OK by R. Brown, May 2000 - M132-40