

PRIMARY CORNER DESCRIPTION Sec Cor for 9, 10, 15 and 16

Alias	Description
Alias	Description
Alias	Description
Alias	Description

GLO survey by Dennis Hathorn, Deputy Surveyor under Contract #73, dated June 8, 1857 - (DCSO records Vol. 15 Page(s) 6304)

-
- Set post cor. secs. 9, 10, 15 and 16, from which
- A Laurel 18" dia., bears S.25°E., 45 lks.
 - A Laurel 15" dia., bears N.44°E., 56 lks.
 - A Fir 10" dia., bears S.85°W., 50 lks.
 - A Fir 12" dia., bears N.85°W., 50 lks.

Cor. Fd. and used in GLO survey by W. H. Byars, Deputy Surveyor, under Contract #376, dated Jan. 22, 1881 - (DCSO records Vol. 15 Page(s) 6343)

Douglas Co. Surveyors Office - James Byron, Deputy and crew - Oct 1962 - C.S. File 52/126-64

Found all original BTs except NE. BT, now stump hole. All check record. NW. BT shows scribing old face "BT". SW. BT, now snag. Scribing seems to have been made with a knife and not old enough for original trees. Do check record and shows old axe work.

Set Brass cap at cor. mkd: County Surveyors Office

T	29	S	R	3	W
	S	9		S	10
	S	16		S	15
				1962	

- New BTs- Rescribe orig. now 19" Fir, N.85°W., 31.0 ft. "S9 T29S R3W CS BT"
- 15" Cedar bears S.22°E., 24.8 ft. scribed "S15 T29S R3W CS BT".
 - 6" Myrtle S.46°W., 12.4 ft. "S16 CS BT".
 - 6" Pine N.34°E., 35.0 ft. "S10 CS BT".

BLM Resurvey by James E. Jelley and Lynn Roseberry Cadastral Surveyors under Group #554 - Surveyed May 1966/Oct. 1967 - (DCSO records Vol. 34 Page(s) 14038)

The Sec. cor. perpetuated and recorded by Byron in 1962, monumented with an iron pipe, 1" dia., firmly set, extending 12" above ground, with brass cap mkd. in 1962 from which the remaining original bearing trees

- A Madrone 24" dia., bears S.25°E., 46 lks. dist., with scribe marks BT visible on opened blaze. (Rec. 45 lks.)

- A Fir snag 10" dia., bears S.85°W., 50 lks. dist., no marks visible.

(Cont. Next Page)

PRIMARY CORNER DESCRIPTION Sec Cor for 9, 10, 15 and 16

Alias	Description

A Fir 16" dia., bears N.85°W., 47 lks., with partially opened blaze and with illegible scribe marks visible on newer blaze. (Rec. 50 lks.)
and bearing trees marked by Byron
A Pine 9" dia., bears N.34°E., 53 lks., with healed blaze.
A Cedar 15" dia., bears S.22°E., 37½ lks., with scribe marks T29S R3W S15 CS BT visible on open blaze.
A Myrtle 8" dia. bears S.48°W., 16½ lks. with scribe marks S16 CS BT visible on open blaze.
Add marks BLM 1966 to brass cap.

Fd. and used in BLM resurvey by Bruce A. Shaner, RLS #430, under Contract #52500-CT5-1117 - Surveyed July/Oct. 1975 Under Group #857, - (DCSO records Vol. 38 Page(s) 15617)

Fd. OK by R. Brown, May 2000 - M132-40

BLM resurvey by George M. Winter, Cadastral Surveyor under Group No. 2654, surveyed Oct./Nov. 2012 - (DCSO records Vol. 58 Page(s) 23028-9)

The cor. of secs. 9, 10, 15, and 16, monumented with an iron post, 1¼" dia., firmly set, projecting 15 ins. above ground, with brass cap (properly) mkd.
from which the remains of original bearing trees
A roothole bears S.25°E., 30.4 ft., with madrone snag, size indeterminate, lying alongside, with a hollowed blaze.
A roothole bears S.85°W., 33.0 ft., with a decayed fallen fir snag, size indeterminate, lying downhill, with scribe marks BT visible on an open blaze.
A fir, 21" dia., bears N.85°W., 31.0 ft., with a healed double blaze.
and remains of bearing trees mkd. by Byron, in 1962
A decayed pine stump, 16" dia., bears N.34°E., 35.0 ft. with no marks visible.
A cedar, 30" dia., bears S.22°E., 24.8 ft., with a healed double blaze.
A chinquapin, 16" dia., bears S.48°W., 10.9 ft., with a healed double blaze. (Record, myrtle)
and a new bearing tree
A fir, 11" dia., bears N.49°E., 33.7 ft., mkd. T29S R3W S10 BT.
Each new bearing tree has a 2½"x ¼" magnetic nail (Mag Nail) driven at the base right side-center.
NAD 1983 (2011) Lat:43°03'26.29"N. Long:123°03'33.78"W.

Fd. BC 8/2018 by N Hibbs, 2018-0027A-B