

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 3 and 4

Alias	Description
Alias	Description
Alias	Description
Alias	Description

GLO survey by W. H. Byars, Deputy Surveyor, under Contract #376, dated Jan. 22, 1881 - (DCSO records Vol. 15 Page(s) 6344)

-----

Marked Cedar 12" dia., for the 1/4 sec. cor., from which  
A Fir 15" dia., bears S.55°E., 22 lks. dist.  
A Fir 20" dia., bears S.42°W., 18 lks. dist.

BLM resurvey by Donald Beck, Cadastral Surveyor, under Group #554 - Surveyed July 1964/April 1965 - (DCSO records Vol. 33 Page(s) 13808)

-----

Point for the 1/4 sec. cor., at proportionate distance; there is no remaining evidence of the original corner.  
Set an iron post, 28" long, 2 1/2" dia., 21" in the ground, with brass cap mkd:  
T 29 S R 3 W  
1/4  
S 4\*S 3  
1964

from which  
A Fir 12" dia., bears N.88 1/2°E., 98 lks., mkd. 1/4 S3 BT.  
A Cedar 15" dia., bears N.26°W., 52 lks., mkd. 1/4 S4 BT.

Found OK Jan. 2003 by R. Rice, - M141-50

BLM resurvey by George M. Winter, Cadastral Surveyor under Group No. 2654, surveyed Oct./Nov. 2012 - (DCSO records Vol. 58 Page(s) 23028)

-----

The 1/4 sec. cor. of secs. 3 and 4, monumented with an iron post, 2 1/2" dia., firmly set, projecting 10" above ground, with brass cap (properly) mkd.  
from which bearing trees mkd. by Beck in 1964-65  
A fir, 12" dia., bears N.88 1/2°E., 64.7 ft., with a healed blaze.  
A cedar, 18" dia., bears N.26°W., 34.3 ft., with a healed blaze.