

PRIMARY CORNER DESCRIPTION N. 1/4 Cor. Sec. 3 only

Alias	Description
_____	_____
_____	_____
_____	_____
_____	_____

GLO survey by W. H. Byars, Deputy Surveyor, under Contract #376, dated Jan. 22, 1881 - (DCSO records Vol. 15 Page(s) 6325)

-----

Set Laurel post for ¼ sec. cor., from which  
A Laurel 12" dia., bears S.32°W., 19 lks.  
A Laurel 10" dia., bears N.20°W., 33 lks

GLO resurvey by William N. Gibb, Deputy Surveyor, under Contract #783, dated Dec. 3, 1908 - (DCSO records Vol. 13 Page(s) 5561)

-----

¼ sec. cor., which is a stake greatly decayed, marked as described by the surveyor general. Bearing trees have been destroyed. Set cedar stake 3 ft. long, 4" sq., 24" in the ground for ¼ sec. cor. marked ¼ S on N. face, and 3 on S. face and dig pits, 18x18x12 ins., E. and W. of cor., and raise mound of earth, 3½ ft. base, 1½ ft. high, S. of cor., from which:  
A Laurel 6" dia., bears S.70°W., 20 lks. dist. mkd. ¼ S3 BT.

BLM resurvey by Donald Beck, Cadastral Surveyor, under Group #554 - Surveyed July 1964/April 1965 - (DCSO records Vol. 33 Page(s) 13799-800)

-----

The ¼ sec. cor. of sec. 3 only, determined at record bearing and distance from the remains of the bearing tree mkd. by Gibb in 1910:  
A down Madrone 7" dia., bears S.70°W., 20 lks. dist., mkd. ¼ S3 BT on an open blaze.

At the corner point  
Set an iron post, 28" long, 2 1/2" dia., 24" in the ground, with brass cap mkd: T 28 S R 3 W

-----  
¼ S 3  
T 29 S R 3 W  
1964

from which new bearing trees:  
A Fir 8" dia., bears S.41½°E., 41 lks. dist. mkd. ¼ S3 BT.  
A Cedar 8" dia., bears S.47½°W., 48½ lks. dist. mkd. ¼ S3 BT.