

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GL0 survey by W. H. Byars, Deputy Surveyor, under Contract #376, dated Jan. 22, 1881 - (DCSO records Vol. 15 Page(s) 6334)

Set Fir post for cor. to secs. 26, 27, 34 and 35, from which
A Fir 15" dia., bears N.42°E., 33 lks. dist.
A Fir 10" dia., bears S.89°E., 30 lks. dist.
A Fir 10" dia., bears N.50°W., 29 lks. dist.
A Cedar 20" dia., bears S.55°W., 56 lks. dist.

Douglas Co. Surveyors Office - James Byron, Deputy - Dale McFarland; J. Powell, crew - Aug. 15, 1961 - C.S. 49/47-24

Found - Orig. 20" now 30" Cedar, previously opened, shows good scribing "29", now down.
Orig. 15" now 24" Fir N.42°E., 21.8 ft., now down, shows scribing.
Orig. 10" now 16" Fir snag, S.81°E., not S.89°E., 19.8 ft., shows good scars.
Orig. 10" now 18" Fir snag, N.50°W., 19.1 ft., shows scars.

Set Brass cap at cor. mkd: County Surveyors Office
T 29 S R 3 W
S 27 | S 26
S 34 | S 35
1961

New BTs- 13" Cedar bears N.9½°E., 22.0 ft. "S26 T29S R3W CSBT
10" R.Fir bears N.27°W., 43.7 ft. "S27 T29S R3W CSBT
9" Cedar bears S.43°E., 14.6 ft. "S35 T29S R3W CS BT
6" Cedar bears S.1°W., 32.7 ft. "S34 CS BT"

Fd. Ok by Ronald L. Rice 10/2004 - M 145-76

BLM Dependent Resurvey by A Bert Skeesick, Cadastral Surveyor and Robert H Browning, Survey Tech, Under Group No. 2157, Surveyed March/May 2007 - DCSO records Vol. 57 Pages 22555-6

The cor. of secs. 26, 27, 34, and 35, perpetuated by Byron, in 1961, monumented with an iron post, 1¼" dia., firmly set, projecting 16" above ground, with brass cap (properly) mkd. from which the remains of the original bearing trees
A roothole bears N.42°E., 21.8 ft., with fallen fir trunk, 20" dia., lying alongside, with no marks visible on an opened blaze.
A decayed fir snag, 15" dia., bears S.84°E., 19.8 ft., with fragmentary scribe marks visible on a previously opened blaze. (Record, S.89°E.)

continued next page

TOWNSHIP 29 RANGE 03 POINT IDENTIFIER # 500200

PRIMARY CORNER DESCRIPTION Sec. Cor. for 26, 27, 34 and 35

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

A sawed cedar stump, 12" dia., bears S.55°W., 41.5 ft., with no marks visible. (Record, 37.0 ft.)
A fallen decayed fir snag, size indeterminate, bears N.50°W., 19.1 ft., with no marks visible.
and remains of bearing trees mkd. by Byron
A fallen decayed cedar, 16" dia., bears N.7¼°E., 21.8 ft., with a healed blaze.
A cedar, 15" dia., bears S.43½°E., 14.6 ft., with a healed blaze.
A cedar, 13" dia., bears S.1¼°E., 32.3 ft., with a healed blaze.
A fir, 18" dia., bears N.28¼°W., 43.3 ft., with a healed blaze.
and new bearing tree
A cedar, 7" dia., bears N.29¼°E., 28.0 ft., mkd. T29S R3W S26 BT.