

PRIMARY CORNER DESCRIPTION Sec. Cor. for 10 & 15 only (East)

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO survey by W. H. Byars, Deputy Surveyor, under Contract #376, dated Jan. 22, 1881 - (DCSO records Vol. 15 Page(s) 6343)

Intersect line 6.12 chs. N. of cor. established for secs. 11 and 14. Set Fir post at point of intersection.

BLM resurvey by Donald Beck, Cadastral Surveyor, under Group #554 - Surveyed July 1964/April 1965 - (DCSO records Vol. 33 Page(s) 13802)

Point for the closing corner of secs. 10 and 15, at proportionate distance; there is no remaining evidence of the original corner.
 Set an iron post 28" long, 2½" dia., 24" in the ground with brass cap mkd.

T 29 S		
CC S 10		S 11
S 15		
R 3 W		
		1964

from which

- A Fir 10" dia., bears S.78°W., 45 lks. dist., mkd. T29S R3W S15 CC BT.
- A Fir 10" dia., bears N.33½°W., 29 lks. dist., mkd. T29S R3W S10 CC BT.

Fd. and used in BLM resurvey by Bruce A. Shaner, RLS #430, under Contract #52500-CT5-1117 - Surveyed July/Oct. 1975 Under Group #857, - (DCSO records Vol. 38 Page(s) 15613)

Fd. OK by D. Edwards, Oct. 1998 - M130-67

BLM Dependent Resurvey by A Bert Skeesick, Cadastral Surveyor and Robert H Browning, Survey Tech, Under Group No. 2154, Surveyed April/May 2007 - DCSO records Vol. 57 Page(s) 22566

The closing cor. of secs. 10 & 15 only, monumented with an iron post, 2½" dia., firmly set, projecting 1" above the ground, with brass cap (properly) mkd.
 from which the remains of BTs mkd. by Beck, reported by Shaner in 1975

- A fir, 17" dia., bears S.78¼°W., 29.7 ft., with a healed blaze. (Record, S.75°W.)
- A sawed fir stump, 12" dia., bears N.32¼°W., 19.1 ft., with no marks visible. (Record, N.36°W.)

and a new bearing tree

- A fir, 9" dia., bears S.41¾°E., 23.3 ft., mkd. X BT.