

TOWNSHIP 29 RANGE 03 POINT IDENTIFIER # 600100

PRIMARY CORNER DESCRIPTION Sec. Cor. for 35 & 36; 1 & 2, T30-3

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO survey by W. H. Byars, Deputy Surveyor, under Contract #376, dated Jan. 22, 1881 - (DCSO records Vol. 15 Page(s) 6320)

Set Chinquapin post for sec. cor. to secs. 2, 1, 35 and 36, from which

- A Fir tree 36" dia., bears N.60°E., 63 lks.
- A Chinquapin 6" dia., bears S.35°E., 30 lks.
- A Fir 16" dia., bears S.85°W., 58 lks.
- A Fir 16" dia., bears N.86°W., 42 lks.

GLO survey by William Bushey, Deputy Surveyor, under Contract #620, dated June 17, 1893 (DCSO records Vol. 16 Page(s) 6928)

The Sec. cor., which is a post greatly decayed with surveyors marks on it but I cannot distinguish them. I find 3 of the original witness trees at cor. point. I Set a Fir post, 5 ft. long, 4' sq., 24" in the ground, for cor. to secs. 1, 2, 35 and 36, mkd. T29S S36 on NE.; R3W S1 on SE.; T30S S2 on SW. and S35 on NW. faces, with 1 notch on E. and 5 notches on W. edges, from which

- A Fir 36" dia., bears N.60°E., 63 lks. dist. mkd. T29S R3W S36 BT.
- A Fir 16" dia., bears S.85°W., 58 lks. dist. mkd. T30S R3W S2 BT.
- A Fir 16" dia., bears N.86°W., 42 lks. dist. mkd. T29S R3W S35 BT.

These are the original witness trees. The witness tree in sec. 1 is burnt. In its stead,
I mark a Fir 7" dia., bears S.35½°E., 46 lks. dist. mkd. T30S R3W S1 BT.

Douglas Co. Surveyors Office - James W. Byron, Deputy - Milo Godfrey, Clete Putnam, crew - Aug. 18, 1960 - C.S. 49/47-19

Found - Fir tree, now 30", N.80°W., 27.7 ft., shows good scar, did not open.
Fir tree, now 22", West 38.9 ft., shows good scar, old bark scribing above scar, did not open.
Fir Tree, now 18", S.35½°E., 30.4 ft., shows good scar, did not open.
Dead Fir snag, 36", N.66°E., 41.6 ft., shows good scar. Fragments of very old bark scribing visible above scar. "S3" is all that is legible at present time.

At Corner Set Iron pipe with Brass cap at cor. mkd:
(Cont. Next Page)

TOWNSHIP 29 RANGE 03 POINT IDENTIFIER # 600100

PRIMARY CORNER DESCRIPTION Sec. Cor. for 35 & 36; 1 & 2, T30-3

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

<p>County Surveyors Office T29S R3W <u>S35</u> <u>S36</u> S 2 S 1 T30S R3W</p>
<p>Blaze and scribe new bearing trees: 14" Fir N.29°E., 9.7 ft. mkd. T29S R3W S36 CS BT. No trace found of original Chinguapin to SE. Corner lies on steep N. slope approx. 1/2 way from top of spur to draw.</p>
<p>BLM Dependent resurvey by Timothy J. Moore & A. Bert Skeesick, Cadastral Surveyors under Group #2033, surveyed Sept. 2002/June 2003 (DCSO rec. Vol. 55 pg(s) 21318)</p> <p>-----</p> <p>Beginning at the cor. of secs. 1, 2, 35, & 36, on the S bdy. of the Tp., perpetuated by the Douglas Co Surveyors Office, in 1960, monumented with an iron post, 1¼" dia., firmly set, projecting 12" above ground, with brass cap (properly) mkd. from which the remains of the original bearing trees</p> <p>A fir, 26" dia., bears S.89°W., 38.3 ft., with no scribe marks visible on bark blaze. (Record, S.85°W.)</p> <p>A fir stump, 31" dia., bears N.80½°W., 27.7 ft., with no marks visible. (Record, N.86°W.)</p> <p>and a bearing tree mkd. by Bushey</p> <p>A fir, 23" dia., bears S.38½°E., 30.4 ft., with healed blaze. (Record, S.35½°E.)</p> <p>and a bearing tree mkd. by the Douglas Co. Surveyors Office</p> <p>A fir, 18" dia., bears N.29°E., 9.4 ft., with healed double blaze.</p> <p>and a new bearing tree</p> <p>A fir, 13" dia., bears N.67¼°W., 10.6 ft., mkd. T29S R3W S35 BT.</p> <p>Each new bearing tree has a 2½"x ¼" magnetic nail (Mag Nail) driven at the base right side-center, unless otherwise described in the corner description</p>
<p>Fd. as per 2003 BLM survey by D. Edwards, 11/2016 - M172-56</p>
<p>2</p>