

TOWNSHIP 29 RANGE 03 POINT IDENTIFIER # 600540

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 11 and 12

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by W. H. Byars, Deputy Surveyor, under Contract #376, dated Jan. 22, 1881 - (DCSO records Vol. 15 Page(s) 6332)

Set a Cedar post for the 1/4 sec. cor., from which
(On ridge, course NW.)
A Laurel 20" dia., bears N.75°E., 22 lks.
A Cedar 5" dia., bears S.63°W., 10 lks.

Douglas Co. Surveyors Office - James Byron, Deputy - Mike Darby; Wm. Stoffel, crew - Nov. 1962 - C.S. File 52/126-83

Found - Orig. 5" now 7" Cedar, shows good scribing "1/4S",
S.63°W., 6.6 ft.
Orig. 20" now 20" Laurel snag, shows good scars,
N.75°E., 14.5 ft.

Set Brass cap at cor. mkd: County Surveyors Office
T 29 S R 3 W
1/4 S11 | S12
1962

New BTs- 7" Fir bears S.71°W., 12.8 ft. scribed 1/4 S11 CS BT
12" Fir bears N.58°E., 10.1 ft. scribed 1/4 S12 CSBT