

TOWNSHIP 29 RANGE 03 POINT IDENTIFIER # 600640

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 1 and 2

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by W. H. Byars, Deputy Surveyor, under Contract #376, dated Jan. 22, 1881 - (DCSO records Vol. 15 Page(s) 6333)

Set a Fir post for the ¼ sec. cor., from which
A Fir 8" dia., bears N.40°E., 9 lks. dist.
A Fir 10" dia., bears N.25°W., 18 lks. dist.

Douglas Co. Surveyors Office - James Byron, Deputy - Mike Darby; Wm. Stoffel, crew - Nov. 1962 - C.S. File 52/126-82

Found - Orig. 10" now 16" R.Fir N.25°W., 11.9 ft., shows good scribing, now down.
Orig. 8" now 10" dead Fir, N.40°E., 5.9 ft., shows good scribe marks.

These two trees are very old. Also call to creek checks OK. Stake set for ¼ cor. bears East 99.0 ft., from which 36" R.Fir bears N.12°W., 13.0 ft. bark scribed. Shell of Fir snag bears N.40°E., 5.5 ft., shows bark scribing.

This corner was probably set not later than 1937. Corner is 20 ft. North of creek, should be 100 ft. South.

Set Brass cap at true corner, mkd: County Surveyors Office
T 29 S R 3 W
¼ S2 | S1
1962

New BTs- 12" R.Fir bears N.17°E., 50.2 ft. scribed ¼ S1 CSBT
11" Cedar bears S.36°W., 19.5 ft. scribed ¼ S2 CSBT

Fd. OK by D. Edwards, June 2007 - M153-49