

TOWNSHIP 29 RANGE 03 POINT IDENTIFIER # 640100

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 36; & 1 T30-3W

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO survey by W. H. Byars, Deputy Surveyor, under Contract #376, dated Jan. 22, 1881 - (DCSO records Vol. 15 Page 6320)

Set laurel post for ¼ sec. cor. from which
A fir tree, 20" dia., bears N.52°E., 42 lks.
A fir tree, 36" dia., bears S.14°E., 80 lks.

GLO survey by William Bushey, Deputy Surveyor, under Contract #620, dated June 17, 1893 (DCSO records Vol. 16 Page(s) 6929)

The sec. cor, which is a post, greatly decayed, marked ¼ S on N face, I find the two witness trees. I remove this post and set a stone, 16x14x7" 12" in the ground, marked ¼ on N. face, from which
A Fir, 36" dia., bears S.14°E., 80 lks. mkd ¼ S BT. This tree is mkd in the bark, I mark it in the wood ¼ S BT
A Fir, 20" dia., bears N.52°E., 42 lks., marked ¼ S BT. This tree is marked in the bark. I mark it in the wood ¼ S BT.

David Edwards - For: Roseburg Resources - Oct. 2016 - M172-56

Looked for, not found.
Set 1/4 corner at proportionate position.
Set - 5/8" X 30" steel rebar with 2 1/2" alum. cap marked as per the 2009 B.L.M. Manual and with "ROSEBURG RESOURCES CO." and "L.S. 2339 and "2016".
A 5" dia. Fir scribed "T305 R3W ¼ S1 BT" bears S.6°W., 18.0'
A 5" dia. Fir scribed "T29S R3W ¼ S36 BT" bears N.86°W, 24.5' six ft steel posts are set 2 feet west and 2 ft east.