

TOWNSHIP 29 RANGE 04 POINT IDENTIFIER # 100140

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 31; 36 T29-5

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Original - James E. Freeman, under Contract #1 dated May 28, 1851 (DCSO records, Vol. 15 Page 6354)

-----  
Set ¼ sec. post, from which  
    A Black Oak, 10" dia., bears W., 37 lks.  
    A Black Oak, 10" dia., bears N.3°W., 65 lks.

Jesse Hooker - June 24, 1947 - C.S. File 40/9 (info added 3/15/2002)

-----  
NOTE - Written in pencil on this corner report "DO NOT USE"

June the 24 day 1947 I found a blank post lying on the ground N.2 ¾°East 2652 ft. from the south west corners of T29S R4W This being the location of the ¼ section cor. between Sections 31 and 36.

I found the roots of the old bearing tree West 37 links all traces of ax or iron work gone.  
At N.3°W., 65 links I found the roots of an Oak and fragments of the trunk, on a fragment of this oak I found an imprint of ax work and what seemed to be a portion of the T in the bottom of the face.  
I placed a new post in place with red crayon marking ¼ S. From which a Fir about 14 inches in Dia., bears S.30½°W., 14 ft. to the center of a cross chopped in the upper edge of the face.

John H. Markham, Jr. - For: Stomar Lumber - Witness: R.G. Boyd - April 22, 1958 - C.S. File 42/345-2

-----  
Determined by O.B.T.s  
Found - B.O. Stump Hole bears W., 24.4'.  
          B.O. Stump Hole bears N.3°W., 42.9'  
          20" Fir bears S.32°W., 16.0' dist.  
          O.B.T. - I rescribe ¼ S36 BT.  
Set - At corner point, 2"x30" truck axle from which:  
      50" Fir bears S.66°E., 4.0' dist., bark scribed ¼ S31 BT.  
      6" Maple bears S.33°E., 42.6' dist., mkd. ¼ S31 BT  
      10" Fir bears N.11°E., 70.0' dist., mkd. ¼ S31 BT  
Top & Road bears East 270.0' - Top & Road bears South 390.0'

continued next page

TOWNSHIP 29 RANGE 04 POINT IDENTIFIER # 100140

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 31; 36 T29-5

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

BLM dependent resurvey by Wayne L. Rogers, Dale T. Bedell, Bryan S. Seibold, Cadastral Surveyors & Robert H. Browning, Surveying Technician, under Group #1625 surveyed Sept. 1991 thru April 1993 - (DCS0 records Vol. 52 Page(s) 19773-4)

-----  
The 1/4 sec. cor. of secs. 31 & 36, perpetuated by Markham, in 1958, from original evidence no longer in existence; monumented with an axle, 2 ins. diam., firmly set, projecting 6 ins. above ground, from which a bearing tree mkd. by person(s) unknown, reported and remarked by Markham:

A fir, 23" diam., bears S.32°W., 24 lks., with healed blaze.

and the remains of bearing trees mkd. by Markham

A root hole, bears N.11°E., 104 lks., with down and decayed fir alongside, size indeterminate, with fragmentary scribe marks visible.

A decayed fir stump, 52 ins. diam., bears S.66°E., 9 lks. dist., no marks visible.

A maple, 10 ins. diam., bears S.33°E., 62 lks., with healed double blaze.

At the corner point

Set a stainless steel post, 28 ins. long, 2½ ins. diam., 24 ins. in the ground, with brass cap mkd.

T29S

R5W R4W

¼

S 36 | S 31

1992

Deposit a white "DEEP-1" magnetic marker at base and axle inside the stainless steel post.

FD. Ok by Ken Hoffine, 1/2006 - M149-60