

TOWNSHIP 29 RANGE 04 POINT IDENTIFIER # 300600

PRIMARY CORNER DESCRIPTION Sec. Cor. for 4, 5, 8 and 9

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GL0 survey by Dennis Hathorn, Deputy Surveyor under Contract #73, dated June 8, 1857 - (DCSO records Vol. 15 Page(s) 6386)

-----  
Set post cor. secs. 4, 5, 8 and 9, from which  
A Fir 36" dia., bears S.70°W., 35 lks. dist.  
A Fir 10" dia., bears S.34°E., 10 lks. dist.  
A Fir 10" dia., bears N.82°E., 28 lks. dist.  
A Fir 10" dia., bears N.52°W., 57 lks. dist.

GL0 survey by W.H. Byars, under Contract #376, dated Jan. 22, 1881 - (DCSO records, Vol. 15 Page 6396) found all witness trees all standing.

GL0 survey by W.F. Briggs, Deputy Surveyor, under Special instructions dated Jan. 18, 1899 - (DCSO records Vol. 15 Page(s) 6414)

-----  
Witness trees still in place.  
Re-established corner in the original position by setting new post, 4 ft. long, 4" sq., 24" in the ground, mkd. T29S S4 on NE.; R4W S9 on SE.; S8 on SW.; and S5 on NW. faces, with 4 notches on East and 5 notches on S. edges.

Frank Cain, County Surveyor - Wit: F.J. Cole; J.T. Black; Wm. Berdine; W.H. Lawrance - May 1915 - Vol. 2 Pg. 231

-----  
Renew corner from original BTs. two of which I find standing, that is:  
A Fir 36" dia., bears S.70°W., 35 lks.  
A Fir 10" dia., bears N.52°W., 57 lks.  
I marked:  
A Fir 24" dia., bears N.8°10'E., 25 lks.  
A W.Fir 10" dia., bears N.80°25'W., 70 lks.  
A W.Fir 12" dia., bears S.4°20'E., 27 lks.

Fd. OK, June 1950 by Claude Kerr - C.S. File 40/252

Thomas R. Eslinger - April 9, 1951 - C.S. File 40/307

-----  
Original government post still standing. Two witness trees found:  
10" Fir S.34°E., 10 lks.  
36" Fir S.70°W., 35 lks., both rotting but scribing could be read on 10" Fir.  
Set 1½" x 24" galv. pipe on North edge of existing post.  
8" W.Fir marked S.8 BT 268.

(Cont. Next Page)

TOWNSHIP 29 RANGE 04 POINT IDENTIFIER # 300600

PRIMARY CORNER DESCRIPTION Sec. Cor. for 4, 5, 8 and 9

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Survey by John H. Markham, Jr. - For: Stomar Lumber Co. -  
June 21, 1957 - C.S. File 42/272

-----  
Point for corner determined from O.B.T.:  
A 28" Fir N.8°10'E., 17.0 ft.  
A 14" W.Fir S.30°W., 17.2 ft. I rescribed S8 BT.  
A 36" Fir S.62°W., 25.0 ft.  
At corner point, found 4 x 4 wood post scribed, and 3/4"  
Iron pipe.  
I SET a 2½" x 44" Iron pipe 24" in ground, from which  
An 8" Cedar bears N.71°W., 23.0 ft. mkd. S5 BT.  
A 15" Cedar bears S.21°30'W., 60.2 ft. mkd. S8 BT.  
An 8" Yew wood bears S.3°W., 39.0 ft. mkd. S9 BT.  
A 5" Alder bears S.21°E., 30.7 ft. mkd. S9 BT.  
Creek bears South 97.0 ft.  
Road bears West 123.0 ft.

Douglas Co. Surveyors Office - James Byron, Deputy - Mike  
Darby; Wm Stoffel crew - April 1963 - C.S. File 52/126-118

-----  
Found - 2½" I.Pipe at corner and all BTs recorded by  
Markham. NE BT, now down.  
New BT - 7" R.Fir bears N.56°E., 26.8 ft. scribed S4 CS BT.

BLM Resurvey by James E. Jelley and Lynn Roseberry Cadastral  
Surveyors under Group #'s 255; 701; 938 - Surveyed July  
1967/Oct 1977 (DCSO records Vol. 39 Page(s) 15889)

-----  
The Sec. cor., perpetuated and recorded by Markham in 1957,  
monumented with an iron pipe 2½" dia., firmly set, projecting  
18" above ground, from which the remains of the original  
bearing trees:  
A sawed Fir stump 36" dia., bears S.70°W., 35 lks. dist.,  
no marks visible.  
and the remains of a bearing tree mkd. by Cain in 1915:  
A root hole bears S.8¼°E., 25 lks. dist. with a down Fir  
alongside, 25" dia., with healed blaze.  
and bearing trees mkd. by Markham:  
An Alder 6" dia., bears S.21°E., 46½ lks. dist., with  
scribe marks S9 visible on open upper blaze and healed  
lower blaze.  
A Yew 11" dia., bears S.3°W., 57 lks. dist. with scribe  
marks S9 visible on open upper blaze and healed lower  
blaze.  
A Cedar 22" dia., bears S.21½°W., 88½ lks. dist. with  
healed double blaze.

(Cont. Next Page)

TOWNSHIP 29 RANGE 04 POINT IDENTIFIER # 300600

PRIMARY CORNER DESCRIPTION Sec. Cor. for 4, 5, 8 and 9

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

A Cedar 12" dia., bears N.71°W., 34½ lks. dist. with scribe marks S5 visible on open upper blaze and healed lower blaze.  
and a bearing tree mkd. by Byron in 1963:  
A Fir 8" dia., bears N.54°E., 41 lks. dist. with healed double blaze.  
At the corner point  
Set an iron post, 28" long, 2 1/2" dia., 24" in the ground, with brass cap mkd:  
T 29 S R 4 W  
S 5 | S 4  
S 8 | S 9  
1969  
Reset Iron pipe alongside iron post.

Fd. Ok by H. Pieske, Feb. 2004 - 2004-0024

David Edwards - For: Roseburg Resources - 10/2024 - M184-31  
-----  
Found - BLM brass cap.  
An 18" dia. Fir bears N.54°E., 27.1'  
A 14" dia. Cedar stump bears N.71°W., 22.8' both w/H.B. all other previous BT's gone.  
New BT - An 11" Cedar scribed "S 5 BT" bears N.51°W., 6.7' 5.5 ft steel post are set 0.65' N.1°30'W., on line and 2' S.82°E., on line.