

PRIMARY CORNER DESCRIPTION Sec. Cor. for 15, 16, 21 and 22

Alias \_\_\_\_\_ Description \_\_\_\_\_  
 Alias \_\_\_\_\_ Description \_\_\_\_\_  
 Alias \_\_\_\_\_ Description \_\_\_\_\_  
 Alias \_\_\_\_\_ Description \_\_\_\_\_

Original - Nathaniel Ford, under Contract #44 dated May 30, 1854 - (DCSO records Vol. 15 Page(s) 6372)

-----  
 Set a post cor. of secs. 15, 16, 21 and 22, from which  
 A R.Fir 24" dia., bears N.27°E., 30 lks. dist.  
 A R.Fir 10" dia., bears N.13°W., 45 lks. dist.  
 A R.Fir 15" dia., bears S.83°W., 68 lks. dist.  
 A Laurel 10" dia., bears S.73°E., 40 lks. dist.

Survey by John H. Markham, Jr. - For: Hult Lumber Co. - April/June 1964 - C.S. File 51/292 and M 28-25

-----  
 (Set by double proportional measurement)  
 Found 40" Laurel and SET 1" x 36" I.P. in hollow butt.  
 New BTs -12" Cedar bears S.37°W., 26.3 ft. mkd. S21 BT.  
 14" Fir bears N.44°30'W., 27.0 ft. mkd. S16 BT.  
 11" Fir bears N.8°30'E., 22.4 ft. mkd. S15 BT.  
 13" Fir bears S.60°E., 24.0 ft. mkd. S22 BT.  
 I marked 40" Laurel at corner point "S21 S22 S15 S16 T29S R4W" on SE. face.

BLM Resurvey by James E. Jelley and Lynn Roseberry Cadastral Surveyors under Group #'s 255; 701; 938 - Surveyed July 1967/Oct 1977 (DCSO records Vol. 39 Page(s) 15870-71)

-----  
 Point for the cor. of secs. 15, 16, 21 and 22, at proportionated distance based on the original Ford survey, latitudinally, and longitudinally based on Hathorn's record claim line survey ties to the cor. of sec. 14, 15 22, and 23, and the cor. of secs. 15, 16, 21 and 22. This method places the corner in good correlation to the original NW. cor. of Donation Land Claim No. 38 and the original NE. cor. of DLC #39; there is no remaining evidence of the original corner. Set and iron post, 28" long, 2½" dia., 24" in the ground, with brass cap mkd:

T 29	S	R 4	W
	S 16		S 15
	S 21		S 22
	1969		

from which  
 A Cedar 7" dia., bears N.71 3/4°E., 29 lks. dist. mkd. T29S R4W S15 BT.  
 A Cedar 25" dia., bears S.26°E., 57½ lks. dist. mkd. T29S R4W S22 BT.  
 A Fir 22" dia., bears S.36¼°W., 106 lks. dist. mkd. T29S R4W S21 BT.  
 A Fir 55" dia., bears N.21¼°W., 118 lks. dist. mkd. T29S R4W S16 BT.

(Cont. Next Page)

PRIMARY CORNER DESCRIPTION Sec. Cor. for 15, 16, 21 and 22

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

From this point, a local corner established by Markham in 1964, bears N.89°18'E., 2.11 chs. dist. monumented with a Madrone 40" dia., with scribe marks T29S R4W S15 S16 S21 S22 visible on bark, with an iron pipe, 1" dia., firmly set, projecting 8" above ground, alongside SE. edge of tree, from which bearing trees mkd. by Markham:

A Fir 12" dia., bears N.8½°E., 33½ lks. dist. with scribe marks S15 visible on partially healed upper blaze and BT visible on lower bark blaze.

A Fir 15" dia., bears S.61°E., 36 lks. dist. with scribe marks S22 visible on partially healed upper blaze and BT visible on lower bark blaze.

A Cedar 12" dia., bears S.36½°W., 39 lks. dist. with scribe marks S21 visible on partially healed upper blaze and BT visible on lower bark blaze.

A Fir 15" dia., bears N.45°W., 40½ lks. dist. with scribe marks S16 visible on partially healed upper blaze and BT visible on lower bark blaze.

Survey by Bruce Shaner - For: Roseburg Forest Products - April 1993 - RM 3-79; C.S. Files 63/96 and 63/153-26

Found - 3¼" Brass Cap on 2½" dia. iron post, from which:  
7" Cedar BT, bearing N.71 3/4°E., 19.1 ft. destroyed and gone.  
25" Cedar BT stump, scribes visible, bears S.26°E., 38.0 ft.  
28" D.Fir BT, face overgrown, bears S.36¼°W., 70.0 ft.  
55" D.Fir BT, Bearing N.21¼°W., 77.9 ft. now gone.

New Accessories -  
10" Cedar BT, scribed "T29S R4W S15 BT" bears N.83°E., 31.5'  
16" Cedar BT, scribed "T29S R4W S22 BT" bears S.64°E., 8.0'  
8" Pine BT, scribed "T29S R4W S16 BT" bears N.30°W., 37.4'

Corner located at newer fence corner, fence bears N. and E.