

TOWNSHIP 29 RANGE 04 POINT IDENTIFIER # 500340

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 22 and 23

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

<p>Original - Nathaniel Ford, under Contract #44 dated May 30, 1854 - (DCSO records Vol. 15 Page(s) 6368)</p> <p>-----</p> <p>Set ¼ sec. post, from which A Red Fir 6" dia., bears N.12°W., 24 lks. dist. A Red Fir 4" dia., bears N.66°E., 15 lks. dist.</p>
<p>Douglas County Surveyors Office - James W. Byron, Deputy - May 1956 - C.S. File 47/101 and RM 1-8</p> <p>-----</p> <p>Corner set halfway between section corners. Set an Iron pipe with brass cap mkd. "¼ S22 23 County Surveyors Office 1956 T29S R4W". Blazed and scribed two trees: 14" Apple tree, N.74°E., 14.0 ft. mkd. ¼ S CS BT. 24" Ash, North 101.0 ft. mkd. ¼ S CS BT. South Myrtle Creek, 350 ft. to North. SW. Corner of house bears N.10°E., 90 ft.</p>
<p>Douglas County Surveyors Office - John M. Powell and crew - Oct. 19, 1971 - C.S. File 49/67-46</p> <p>-----</p> <p>Found - Part of 1956 DCSO brass cap, out of ground. All BTs are gone, dead and disposed of. SW Cor. of house N.3°E., 87.3 ft. (Rec. N.10°E., 90.0 ft.) Porch may have been added. However, remainder of brass cap is still firmly in ground. Set New brass cap at the same point of 1956 cap, mkd: County Surveyors Office 1971 T29S R4W 1/4 S22 S23. New BT - 14" Apple S.69°E., 41.3 ft. scribed "¼ S23 CS BT". NE Corner of barn, S.58°W., 81.8 ft. SW Corner of house, (porch) N.3°E., 87.3 ft.</p>
<p>Fd. Ok by K.Hoffine - 9/97 - M 128-12</p>
<p>Douglas Co. Surveyors Office - Crew: Stephen Flause &amp; Jeff Lorsung- 2/28/2022 - C.S. File 67/51-28</p> <p>-----</p> <p>Found - 22" Apple, S.69°E., 41.3 ft. healed scar. NE corner of barn S.58°W., 81.8 ft. this corner of main barn structure corner post is gone measurement is to joist notch that held corner post. (1971 BC gone, fd piece of IP flange buried in ground near corner position House noted in 1971 now gone.) continued next page</p>

TOWNSHIP 29 RANGE 04 POINT IDENTIFIER # 500340

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 22 and 23

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

<p>New - 2<sup>3</sup>/<sub>8</sub>" brass cap on 1" I.D. iron pipe position determined from found references. Cap is buried 6" below ground in field. Brass cap mkd: DOUGLAS COUNTY SURVEYOR T29S R4W ¼ S22 S23 2022</p> <p>New - Most northerly corner of purpose built power pole. A 6"x6" treated post set in concrete ±20' tall bears N.76°W., 22.7'. The east and west end of a 4-5 ft tall concrete block wall measured to the south edge of the end blocks. This wall has a large gap in the east half. <u>The far east</u> end bears N.60°E. 113.3 ft <u>The far west</u> end bears N.43°W., 77.3 ft See sketch in file.</p> <p>Note - Compass decl. 14½°E.</p>
<p>Dan Saily, Lone Rock Timber Co. - Crew: Brett Ragon, Ignacio Roman &amp; Trevor Clemo - 12/2023 - M183-28 -----</p> <p>Found - Douglas Co. Surveyor's brass cap. 22" Apple fd as per record NE corner of barn found as per record. 6"X6" treated post found per record. East end of concrete block wall found per record. West end of concrete block was found per record. Corner lies in an open pasture. Top of corner monument is 0.5 ft. below ground level. Crushed rock was placed over top of the corner.</p>
<p style="text-align: right;">2</p>