

PRIMARY CORNER DESCRIPTION Sec Cor for 2, 3, 10 and 11

Alias	Description

GLO survey by W. H. Byars, Deputy Surveyor, under Contract #376, dated Jan. 22, 1881 - (DCSO records Vol. 15 Page(s) 6392)

Set a Fir post for cor. to secs. 2, 3, 10 and 11, from which
A Laurel 18" dia., bears N.88°E., 43 lks. dist.
A Laurel 8" dia., bears S.5°E., 38 lks. dist.
A Laurel 8" dia., bears S.30°W., 20 lks. dist.
A Laurel 12" dia., bears N.89°W., 15 lks. dist.

Douglas Co. Surveyors Office - James Byron, Deputy - Mike Darby; Wm. Stoffel crew - April 1963 - C.S. File 52/126-121

Found - Orig. 18" now 24" Laurel stump N.88°E., 28.4 ft. We open and find good scribing "BT".
Stump hole that checks original NW. BT.

Set Brass cap at cor. mkd: County Surveyors Office

T 29 S R 4 W
S 3 | S 2
S10 | S11
1963

New BTs -5" Cedar bears N.23°W., 16.6 ft. scribed S3 CS BT.
15" R.Fir bears N.83°E., 35.8 ft. scribed S2 T29S R4W CS BT.
7" R.Fir bears S.25°W., 22.0 ft. scribed S10 T29S R4W CS BT.
16" W.Fir bears S.28°E., 31.8 ft. previously scribed S11 T29S R4W BT. We add "CS".

This corner was renewed about 5-10 years ago but not of record. We find scribed corner stake from which

16" W.Fir bears S.11°E., 27.2 ft. scribed S11 T29S R4W BT.
12" Laurel bears S.48°W., 29.8 ft. scribed T29S R4W BT.

Fd. OK, June 1983 by W. Ruppert - M 94-61

Fd. & used on BLM dependent resurvey by Wayne L. Rogers, Dale T. Bedell, Bryan S. Seibold, Cadastral Surveyors & Robert H. Browning, Surveying Technician, under Group #1625 surveyed Sept. 1991 thru April 1993 - (DCSO records Vol. 52 Page(s) 19788)

Found OK by R. Ward, Jan. 2002 - M139-35
Fd. Ok by Lloyd Tolbert, May 2005 - M147-66