

TOWNSHIP 29 RANGE 04 POINT IDENTIFIER # 540440

PRIMARY CORNER DESCRIPTION Center 1/4 Cor. for Sec. 14

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Survey by Donald R. Martin - For: Lawrence - Dec. 1968 -
M 39-21

Set 3/4" Iron pipe for center of section.

Bearing trees:

16" Cedar S.14°W., 47.4 ft.

18" Cedar N.48°W., 48.5 ft.

Douglas Co. Surveyors Office - Randall Smith & Stephen Flause
- Oct. 12, 1997 - C.S. 65/15-22

Found - 3/4" iron pipe in bank of creek. This monument is
1' from creek bank and in danger of being lost
during high water.

25" Cedar, S.16°W. 47' good condition, per M 39-21

24" Cedar, N.47°W. 47.5' good condition per M39-21

Found CE 1/16, 3/4" IP, S.88°06'30"E., 1309.41' per
M 39-21. This is basis of bearing for
accessories found and set.

New - Referenced County Road Dept. R/W mon., 1.5" al.
cap on 5/8" iron rod S.59°16'E., 64.24' from
center 1/4 corner.

5/8"x30" iron rod with 3/4" brass washer LS 866,
S.88°06'30"E., 26.56' from center 1/4 corner.

FD. by Ken Hoffine, 8/2007 - M154-15