

PRIMARY CORNER DESCRIPTION Sec Cor for 11, 12, 13 and 14

Alias	Description
Alias	Description
Alias	Description
Alias	Description

Original - Nathaniel Ford, under Contract #44 dated May 30, 1854 - (DCSO records Vol. 15 Page(s) 6365)

Set a post cor. of secs. 11, 12, 13 and 14, from which
A Red Fir 6" dia., bears S.35°E., 11 lks. dist.
A Red Fir 6" dia., bears N.60°E., 7 lks. dist.
A Red Fir 4" dia., bears S.5°W., 15 lks. dist.
A Red Fir 8" dia., bears N.65°W., 13 lks. dist.

"Found Witness trees all standing" by W.H. Byars, Cadastral Deputy Surveyor, under Contract #376, dated Jan. 22, 1881 (DCSO records, Vol. 15 Page 6388)

W.H. Wood - Crew, Geo. Spaur; A.C. Redifer - Wit: W.E. Hollinger; Elmer Heath; Ralph Smith - Aug. 29, 1925 - C.S. File 3/27; Vol. 3 Pg. 234 (and "old" corner book, Pg. 123)

Set Iron pipe 2" x 2 ft., from one old BT. Marked:
Fir 15" S.71°30'W., 36 lks. "BT S14 CS"
Fir 15" N.72°30'E., 23 lks. "BT S12 CS"
Fir 12" N.8°00'W., 32 lks. "BT S11 CS"
Cedar 30" S.42°E., 56 lks. "BT S13 CS"

Douglas Co. Surveyors Office - James Byron, Deputy - Mike Darby; Wm. Stoffel crew - April 1, 1963 - C.S. 52/126-101

Found - 2" I.P. at corner.
30" now 40" Cedar S.42°E., 37.0 ft., shows scars.
15" now 30" Fir stump N.72°E., 15.2 ft., shows scar.
SW BT not found. NE BT, now dead.
New BTs -30" W.Fir S.10°W., 9.9 ft. scribed S14 T29S R4W CSBT
14" Cedar bears N.35°W., 36.3 ft. scribed S11 T29S R4W CS BT.
14" W.Fir bears N.0½°E., 43.0 ft. scribed S11 T29S R4W CS BT.

BLM resurvey by Donald Beck, Cadastral Surveyor, under Group #255 - Surveyed Sept. 2-9, 1964 - (DCSO records Vol. 33 Page(s) 13874-75)

The Sec. cor., perpetuated and recorded by Wm. Wood in 1925, with an iron pipe 2" dia., firmly set, 8" above the ground. Subsequently renewed by Byron in 1962, from which the remaining original bearing tree:
A Fir 25" dia., bears S.13½°W., 15 lks. dist. with illegible scribe marks on overgrowth, remarked T29S R4W S14 CS BT on double blaze, alongside original blaze, by Byron. (Rec. S.5°W.) (Cont. Next Page)

PRIMARY CORNER DESCRIPTION Sec. Cor. for 11, 12, 13 and 14

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

and bearing tree mkd. by Wood in 1925:
 A sawed Fir stump 42" dia., bears N.69¼°E., 25 lks. dist., with no marks remaining.
 A Cedar 40" dia., bears S.42¼°E., 57 lks. dist. with a healed blaze.
 A stump hole bears S.71½°W., 36 lks. dist.
 A Fir snag 23" dia., bears N.8½°W., 34 lks. dist. with a healed blaze.

and bearing trees mkd. by Byron in 1962:
 A Fir 13" dia., bears N.½°E., 65 lks. dist. mkd. T29S R4W S12 CS BT on double blaze.
 A Cedar 13" dia., bears N.34½°W., 55 lks. dist. mkd. T29S R4W S11 CS BT on double blaze.

At the corner point
 Set an iron post, 28" long, 2 1/2" dia., 24" in the ground, with brass cap mkd:

T	29	S	R	4	W
	S	11		S	12
	S	14		S	13
	1964				

from which a new bearing tree
 A Fir 7" dia., bears S.53°E., 86 lks. dist. mkd. T29S R4W S13 BT.
 Reset Iron pipe alongside iron post.
 Corner is in SW. corner of logged area.

Fd. OK, June 1983 by W. Ruppert - M 94-61
 Fd. OK, 3/1998 by D.Edwards - M128-43

Fd. & used on BLM dependent resurvey by Wayne L. Rogers, Dale T. Bedell, Bryan S. Seibold, Cadastral Surveyors & Robert H. Browning, Surveying Technician, under Group #1625 surveyed Sept. 1991 thru April 1993 - (DCSO records Vol. 52 Page(s) 19781)

BLM dependent resurvey by Bryan S. Seibold, Cadastral Surveyor & Robert H. Browning, Surveying Technician, under Group #1775, surveyed Aug./Sept.. 1995 - (DCSO records Vol. 52 Page(s) 19944)

 The cor. of secs. 11, 12, 13, & 14,, monumented with an iron post, 2½" diam., firmly set, projecting 3" above ground, with brass cap mkd.

T29S	R4W
S 11	S 12
S 14	S 13
1964	

from which the remains of an original bearing tree
 A rotted fir stump, size indeterminate, bears S.13½°W., 15 lks., no marks visible. continued next page

TOWNSHIP 29 RANGE 04 POINT IDENTIFIER # 600500

PRIMARY CORNER DESCRIPTION Sec. Cor. for 11, 12, 13 and 14

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

and the remains of bearing trees mkd. by Woods, in 1925,
A sawed fir stump, 42" diam., bears N.72°E., 23 lks., no marks visible.
A cedar, 43" diam., bears S.42¼°E., 57 lks., with healed blaze.
A root hole, bears N.8½°W., 34 lks., with down fir alongside, 23" diam., with healed blaze.
and the remains of bearing trees mkd. by Byron,
A fir, 17" diam., bears N.0½°E., 65 lks., with healed double blaze.
A cedar, 20" diam., bears N.34½°W., 55 lks., with healed blaze.
and a bearing tree mkd. by Beck
A fir, 15" diam., bears S.53°E., 86 lks., with healed blaze.
and a new bearing tree
A fir, 8" diam., bears S.46½°W., 37½ lks., mkd. T29S R4W S14 BT.

Found OK by T. Hostetter, May 2003 - M142-19
FD. by Ken Hoffine, 8/2007 - M154-15