

PRIMARY CORNER DESCRIPTION East 1/4 Cor. for Sec. 24 only

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

Original - Nathaniel Ford, under Contract #44 dated May 30, 1854 - (DCSO records Vol. 15 Page(s) 6298)

Set ¼ sec. post, from which
A W.Oak 16" dia., bears N.10°E., 90 lks. dist.
A Pine 40" dia., bears S.20°W., 210 lks. dist.

GL0 survey by W.H. Byars, found all trees standing - Contract #376, dated Jan. 22, 1881 - (DCSO records, Vol. 15 Pg. 6316)

F.C. Frear, Deputy Co. Surveyor - For: Cody and Black - Wit: Jesse Smith; Ralph Smith; Jeff Wiley - June/July 1918 - M 1-33; C.S. Files 6/23 and 6/6 (and "old" cor. bk. pg. 122)

Set in from old BTs, a 2" x 30" Galv. Iron pipe, from which
A Yellow Pine 40" dia., bears S.20°00'W., 2.10 chs.
A W.Oak 18" dia., bears S.15°45'E., .77 chs.
A Fir 20" dia., bears N.28°30'E., .19½ chs.

Ben B. Irving, Deputy Co. Surveyor - Wit: N.E. Richardson; Loren Weber; Dale Woodruff - Oct. 22, 1940 - (No record source found) (See "old" corner book, pg. 124)

Found - Iron pipe as set by Frear in 1918, in place.
Fir N, 28½°E., 19½ lks. as set by Frear, cut and scar burned out of stump.
Oak, S.15 ¾°E. destroyed, cut and stump by fire, stump hole and few roots only being visible.
Pine, S.20°W., 2.10 chs., cut and stump burned, part of blaze still visible.
Set new bearing trees as follows:
A Fir 30" dia., bears N.51½°W., 29.3 ft. mkd. ¼ S24 CS BT.
A Fir 30" dia., bears S.33½°W., 142.7 ft. mkd. ¼ S24 CS BT.

Douglas Co. Surveyors Office - James W. Byron, Deputy - Milo Godfrey; Clete Putnam, crew - April 15, 1960 - C.S. 49/67-13

Found - 1½" Iron pipe at corner.
Irving NW BT, shows good bark scribing, "BT" now stump.
Irving SW. BT, now snag.
Set Brass cap at cor. mkd: County Surveyors Office
T 29 S R 4 W
E ¼ S 24 |
1960
Set brass cap alongside iron pipe. (Cont. Next Page)

TOWNSHIP 29 RANGE 04 POINT IDENTIFIER # 700340

PRIMARY CORNER DESCRIPTION E. 1/4 Cor. Sec. 24 only

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

New BTs -15" Cedar bears N.70°W., 25.9 ft. scribed ¼ S24 CS
BT.
16" Cedar bears N.25°W., 28.5 ft. scribed ¼ S24 CS
BT.
E-W fence 10 ft. North.

BLM resurvey by Donald Beck, Cadastral Surveyor, under Group #554 - Surveyed July 1964/April 1965 - (DCSO records Vol. 33 Page(s) 13791)

The ¼ sec.cor. of sec. 24 only, remonumented and recorded by Germond, in 1918, subsequently remoumented by Byron in 1960, with an iron post 1" dia., 18" above ground, firmly set, with properly mkd. brass cap
from which the remains of the original SW. bearing tree:
A burned Pine stump 46" dia., bears S.20°W., 210 lks. dist. with recent axe marks visible.
and bearing trees mkd. by Germond:
A sawed Fir stump 24" dia., bears N.28½°E., 21 lks. dist. mkd. CS on an open blaze.
A stump hole, bears S.15 3/4°E., 77 lks. dist.
and bearing trees mkd. by Byron:
A Cedar 16" dia., bears N.71¼°W., 39 lks. dist. mkd. ¼ S24 CS BT on double blaze.
A Cedar 18" dia., bears N.26¼°W., 43½ lks. dist. mkd. ¼ S24 CS BT.
and a bearing tree not of record:
A sawed Fir stump 30" dia., bears N.52½°W., 46 lks. dist. mkd. BT on bark blaze.
Add the marks BLM to the brass cap.

Fd. and used in BLM survey by Roseberry and Jelley, under Group #'s 255, 701, 938 - surveyed July 1967/Oct. 1977 - (DCSO records, Vol. 39 Page 15855)