

TOWNSHIP 29 RANGE 05 POINT IDENTIFIER # 100360

PRIMARY CORNER DESCRIPTION N 1/16 Sec. 19; Sec. 24 T29-6

Alias	_____	Description	_____
Alias	_____	Description	_____
Alias	_____	Description	_____
Alias	_____	Description	_____

Doug. County Surveyors Office - R.B. Kimberling - F.C. Silagy
- Dec. 14, 1977 - C.S. File 59/42-33 - C.S. File 59/49 - M
68-47

Found - A 1969 County Surveyors brass cap on a 1"x36" I.P.
set 14" above ground. Corner was proportioned
between the NW cor. Sec 19 and SW cor. Sec. 30
and needs resurveyed since the SW cor. Sec. 19
has been found. See voided survey M 37-20.
A 22" W.Oak, bears N.79°E., 84.2' (rec. N.80°E.,
81.1') with visible scribing in an almost healed
double blaze.
A 30" B.Oak, bears S.7°E. 71.4' (rec. S.4°E., 75.2')
with a well healed double blaze.
Set - I move brass cap S.59°34'20"W., 4.31'. Cap is set 7"
above ground in a 18" mound of stone and stamped
"Reset 1977" above "1969".
I set a 5/8"x30" I.R. in orig. brass cap location
with a 1½" Alum. cap set 6" above ground in a 18"
mound of stone and mkd. "Douglas Co." 1977
Surveyor.
No new accessories. N-S fence bears East 3.7'.

DCSO-GIS Corner visitation - 8/20/2004 - Typed: 2/2/2011 -
C.S. File 67/33-1

Monument - BC/IP 1.25"
Comment - ok