

TOWNSHIP 29 RANGE 05 POINT IDENTIFIER # 300640

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 4 & 5

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Original - Nathaniel Ford, under Contract #44 dated May 30, 1854 (DCSO records, Vol. 15 Page 6445)

-----  
Set a post at ave. dist., from which  
An Ash, 6" dia., bears S.13°W., 36 lks.  
An Alder, 8" dia., bears N.12°E., 48 lks.

Arthur R. Evans - 8/11-13/53 - C.S. File 41/227 - M 25-70

-----  
Set by proportionate measurement.  
Set - 1¼" iron pipe and 2 BTs  
24" W.O. S.69½°W., 57.7'  
12" W.O. S.33 3/4°W., 67.9'  
Found corner set erroneously, S.61°06'W., 12.0' from actual corner position. I.P. knocked out by tractor. Position determined from BTs:  
W.O. S.70°W., 45'  
W.O. S.28°W., 57.5'  
(C.S. 41/53-2 for 6/1/1952 Markham corner) added 6/19/2024

William Ruppert, LS 866 - For: Ron Kuehn - 11/79 - M 81-29

-----  
Found - 1¼" iron pipe  
Set - 1" iron pipe & 2½" brass cap mkd: T29S R5W ¼ S5\*S4  
LS 866 1979, 1¼" iron pipe lies S.77°E., 3.0' from brass cap.  
BTs - BTs per M 25-70 (Evans 1953 survey).  
FROM BRASS CAP  
30" W.Oak S.73°W., 60.0' - scar.  
23" W. Oak S.39¼°W., 69.3' - scar.

William Ruppert - For: Ron Kuehn - 10/80 - M 84-58 - C.S. File 58/143 (n)

-----  
Found - 2½" brass cap  
30" W. Oak, S.70°W., 60.0'. Scar.  
23" W. Oak, S.36¼°W., 69.3'. Scar.  
Note - ROTATION ERROR OF 3° ON MAPS M 82-10 & M 81-29 & CORRESPONDING ROTATION OF BEARING TREE BEARINGS