

TOWNSHIP 29 RANGE 05 POINT IDENTIFIER # 400640

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 3 & 4

|             |                   |
|-------------|-------------------|
| Alias _____ | Description _____ |
| Alias _____ | Description _____ |
| Alias _____ | Description _____ |
| Alias _____ | Description _____ |

Original - Nathaniel Ford, under Contract #44 dated May 30, 1854 (DCSO records, Vol. 15 Page 6440)

-----  
Set ¼ sec. post at proper dist; from which;  
A B. Oak, 18" dia., bears N.13°W., 76 lks.  
A B. Oak, 8" dia., bears S.38°E., 163 lks.

John H. Markham, Jr. - Witness: Geo. Vaughn - Aug. 1, 1950 - C.S. File 40/263

-----  
Determined by proportional distance.  
At corner point:  
Set - ¾"x30" I.P. 16" in ground, from which;  
A Cedar, 9" dia., bears S.85°E., 60.0' dist., mkd: ¼ S3, 2880 BT.  
A Fir, 7" dia., bears N.30°W., 8.5' dist., mkd: ¼ S4, 2880 BT.

Doug. County Surveyors Office - James W. Byron, Deputy - Dale McFarland - John Powell - Dec. 1961 - C.S. File 49/64-55

-----  
Found - Both of Markham's BTs  
9" now 10" Cedar Stump, out of ground, shows face ' I believe a scribe mark, it has been badly burned. Stump hole checks S.85°E., 60.0'.  
The N.W. BT down and badly burned, checks O.K.  
Also find ¾" I.P. at corner.  
Set - Brass Cap alongside I.P. & Mkd: County Surveyor's Office 1961 ¼ S4|S3 T29S R5W.  
New BTs -22" R. Fir, bears S.64°W., 40.0' scribed ¼ S4 CS BT.  
21" Cedar, bears N.20½E., 143.0' scribed ¼ S3 CS BT.

Mark Smalley, L.S. #2354 - For: Roseburg Forest Products Co. - July/Sept 1993 - M 119-2

-----  
Found - 1961 County Surveyor BCIP & ¾" IP  
21" Cedar, N.21°E., 143.0', stump  
22" Fir, S.64°W., 40.0', stump  
Found no evidence of Markham's BTs  
NOTE: THIS MONUMENT BEARS N.86°40'32"E., 15.71' FROM THE POSITION CALCULATED FOR THIS CORNER.