

TOWNSHIP 29 RANGE 06 POINT IDENTIFIER # 045010

PRIMARY CORNER DESCRIPTION NE Cor. Willis DLC #45

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Original - Bowman and Burnett, under Contract dated Sept. 1855 (DLC survey)

Set a post from which
 A B.Oak 8" dia., bears S.75°W., 29 lks.
 A Fir 24" dia., bears N.10°W., 25 lks.

Frank Cain - For: Geo. W. Gordon - 1913 - F.B. 35 Pg. 17

I reestablish original position from the stump of one of the original witness trees - viz. A Fir 24" dia., N.10°W., 25 lks. I remark two new witness trees as follows:
 A Fir 12" dia., marked CS C45 BT, N.50°W., 11 lks.
 A Fir 14" dia., marked CS C45 BT, S.37¼°W., 22 lks.

J.W. Cole - Wit: E.Richardson, chain, H.E. Bergh, chain - Feb. 2, 1923 - (no record source for this information could be found - from former renewal record #34 (and "old" corner book, page 131)

Renewed corner from old rotten Oak stake marked C.S. Cl. 45, from which stump of 30" Fir bears N.10°W., 25 lks.
Marked BTs also
 A Fir 14" marked C.S. CL. 45 BT, N.49°30'W., 7 ft.
 A Fir 14" marked C.S. CL. 45 BT S.41°00'W., 14.6 ft.
Both Firs look as though they had been marked approx. 5 years previous. Erected mound of rock around old stake. The ¼ corner between 16 and 21 bears East 430 ft. and South 121.4 ft.

Douglas Co. Surveyors Office - James Byron, Deputy - John Fee Ray Irving, crew - June 1954 - C.S. File 46/45-1(F)

Found - Mound of rocks at corner at BT, 14" Fir stump scribed 45, visible checks for bearing and distance to corner.
 We found stumps (rotted) that check the other two BTs.
Set 1" Iron pipe with brass cap mkd. County Surveyors Office 1954 DLC 45 N.E. Cor. T29S R6W.
Blazed and scribed:
 7" W.Oak S.60°W., 29.1 ft. NE CL 45 CS BT.
 12" R.Fir S.63½°E., 40.0 ft. NE CL 45 CS BT.
31° East to wire fence.

Fd. Ok by Howard Johnstone, Dec. 1989 - M 101-72

(Cont. Next Page)

1

TOWNSHIP 29 RANGE 06 POINT IDENTIFIER # 045010

PRIMARY CORNER DESCRIPTION NE Cor Willis DLC #45

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Douglas Co. Surveyors Office - Randall Smith & Stephen Flause
- Feb. 5, 1996 - C.S. 64/66-2

Mon. Fd. - 2½" Brass cap on a 1½" O.D. iron pipe protrudes
13" above ground. 1954 Byron small mound of
stone around base of BC/IP.

Accessories Fd. -
12" now 25" dia. D.Fir, with a fully healed
double blaze, bears S.63½°E., 40' (agrees
with rec.) 1954 Byron.

DCSO 1954 7" W.Oak, now depression in ground near
rec. Brg. & Dist.

No other BT's Fd.

FD. 5/8" I.R. protruding 12" above ground, bears
S.75¼°E., 77.25'.

New Accessories -

11" dia. W.Oak, double blazed and scribed "NE DLC
45 CS BT", bears S.79½°W., 49.4'.

19" dia. W.Oak, double blazed and scribed "NE DLC
45 CS BT", bears S.10 3/4°E., 110.8'.