

TOWNSHIP 29 RANGE 06 POINT IDENTIFIER # 200100

PRIMARY CORNER DESCRIPTION So. Sec. Cor. 31 & 32 only

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

Original - Fred C. Mensch under Contract #757 dated Sept. 14, 1904 - (DCSO records, Vol. 15 Page 6498)

-----  
(Point on Tp. bdy., 11.70 chs. S.89°36'E., of the cor. of secs. 5, 6, 31 and 32,)

Set an ironstone 24 x 14 x 12 ins. 18" in the ground for closing corner of secs. 31 and 32, marked CC on N. with 5 grooves on E. and 1 groove on W. face, from which

A R.Fir 7" dia., bears N.63°E., 45 lks. dist., mkd.  
T29S R6W S32 BT.

A R.Fir 6" dia., bears N.45°W., 20 lks. dist., mkd. T29S  
R6W S31 BT.

I destroy marks on former corner and bearing trees referring to these secs.

John H. Markham, Jr. - For: Stomar Lbr. Co. - Aug/Oct. 1956  
C.S. File 42/190-5

-----  
Found - 11" Fir bears N.63°E., 30.0 ft., O.B.T, found scribe.

6" Fir snag, bears N.45°W., 13.0 ft., O.B.T., found scribe.

At corner point, found large stone and Set 3/4" x 20" Iron pipe from which

20" Yew wood bears N.49°E., 44.6 ft. mkd. S32 T29S R6W BT.

13" Cedar bears S.2°W., 31.8 ft. mkd. S31 X BT.

60" Fir bears N.65°W., 34.4 ft. mkd. S31 T29S R6W BT.

Corner lies in a E-W saddle.

BLM resurvey by Thielsen and White under Contract #'s 348 and 350 - Surveyed July 1958/August 1959 - (DCSO records, Vol. 30 Page 12813)

-----  
The original closing corner established by Mensch in 1904, bears N.0°02'W., 33 lks., monumented with a basalt stone, 24x14x12 ins. 16" in the ground, firmly set, mkd. CC on N. face, from which the remaining original bearing tree:

A Fir 10" dia., partially dead, bears N.61½°E., 45 lks. mkd. R6W S32 on open blaze. (Rec. N.63°E.)

In order that this point will not be lost

Set an iron post, 28 ins. long, 2½ ins. diam., 22 ins. in the ground, with brass cap mkd:

    C C  
T 29 S | R 6 W  
    S 31 | S 32  
        S 5  
    T 30 S

1958

(Cont. Next Page)

TOWNSHIP 29 RANGE 06 POINT IDENTIFIER # 200100

PRIMARY CORNER DESCRIPTION So. Sec. Cor. 31 & 32 only

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

from which new bearing trees  
A Fir 20" dia., bears N.79°E., 61 lks. mkd. T29S R6W S32  
CC BT.  
A Fir 45" dia., bears N.53½°W., 78 lks. mkd. T29S R6W S31  
CC BT.  
Bury original stone alongside the iron post.

Doug. County Surveyors Office - Gary Langlitz; Peter Earle -  
Feb. 20, 1974 - C.S. File 56/43-20  
-----  
CORNER REPORT ONLY  
Found corner in good condition. I Do Not Renew  
Corner lies in bottom of draw, course West, approx. 200 ft.  
South of a fairly new logging road.

Corner Fd. OK, Jelley & Rogers under Contract #1024 and 1039  
- Surveyed 1980 - DCSO records, Vol. 42 Pages 16565-66

BLM resurvey by Wayne L. Rogers, under Group #1030 - Surveyed  
Aug/Sept. 1980 (DCSO records, Vol. 45 Pages 17259-60)  
-----  
Found original closing corner and 1958 brass cap from which  
the remains of the original bearing trees  
A Fir 18" dia., bears N.61½°E., 45 lks. with healed blaze.  
and bearing trees mkd. by Markham in 1956  
A Yew 23" dia., bears N.51½°E., 67½ lks. dist., with  
scribe marks S32 T29S R6W BT.  
A Cedar 18" dia., bears S.5½°W., 48 lks. with healed  
double blaze.  
and bearing trees by Thielsen and White  
A Grand Fir 25" dia., bears N.79°E., 61 lks. with healed  
blaze.  
A Fir 50" dia., bears N.53½°W., 78 lks. dist., with scribe  
marks T29S R6W S31 BT.  
Add the marks AM to the brass cap.  
  
(At a point .35 chs., S.0°51'W.)  
Set an iron post, 28 ins. long, 2½ ins. diam., 24 ins. in the  
ground, with brass cap mkd: T 29 S R 6 W  
C C  
|  
S 31 | S 32  
S 5  
T 30 S R 6 W  
1980  
  
from which new bearing trees  
(Cont. Next Page)

TOWNSHIP 29 RANGE 06 POINT IDENTIFIER # 200100

PRIMARY CORNER DESCRIPTION So. Sec. Cor. 31 & 32 only

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

A Fir 8" dia., bears N.64¼°E., 54 lks. mkd. T29S R6W S32  
CC BT.  
A Fir 6" dia., bears N.72 3/4°W., 88½ lks. mkd. T29S R6W  
S31 CC BT.

Survey by Howard Johnstone, - For: Roseburg Resources Inc. -  
Jan. 23, 1990 - C.S. File 63/104-4 & 63/104-5

-----  
Found - 1980 Cadastral brass cap on iron pipe.  
6" Fir N.72 3/4°W., 58.4 ft. high stumped. Gone.  
(1980 BLM)  
8" Fir N.64½°E., 35.6 ft. good face, high stumped.  
(1980 BLM)  
23.1 ft. North to AM-CC brass cap. (1958 BLM)  
Tied corner to remaining BTs for the AM-CC:  
50" D.Fir stump bark scribed, N.36°W., 67.0 ft.  
18" Fir healed face, N.37°E., 45.5 ft.  
25" W.Fir healed face, N.54°E., 49.6 ft.  
Corner lies in NE corner of 1989-90 clear cut unit logging  
all around the corner. About 200 ft. South of road.

DCS0-GIS Corner visitation - 8/10/2004 - Typed: 2/1/2011 -  
C.S. File 67/33-1

-----  
Monument - GLO/BLM 2.5" BC/IP  
Comment - (needs) rehab

David Edwards - For: Roseburg Resources Co - 3/2011 - M162-22

-----  
Condition report  
Fd. BLM cap on ground.  
Reset per Johnstone rehab. C.S. 63/104  
AM CC cap N.0°51'E., 23.1'  
20" Fir N.37°E., 45.5'  
25" Fir N.54°E., 49.6'  
Capped fir stump N.64½°E., 35.6'