

PRIMARY CORNER DESCRIPTION 1/4 Cor. for secs. 31 and 32

Alias	Description
Alias	Description
Alias	Description
Alias	Description

GLO survey by Fred Mensch under Contract #757 dated Sept. 14, 1904 (DCSO records Vol. 15 Page(s) 6499)

Set an ironstone 12 x 10 x 6 ins., 8" in the ground for ¼ sec. cor. marked ¼ on W. face, from which

A Red Fir 12" dia., bears N.28°E., 39 lks. dist. marked ¼ S32 BT.

A Maple 8" dia., bears S.37°W., 29 lks. dist., marked ¼ S31 BT.

Survey by John H. Markham, Jr. - For: Stomar Lumber Co. - March 4, 1957 - C.S. File 42/254

Location for corner determined by O.B.T., a 10" Fir, bears N.28°E., 25.7 ft., found scribe.

AT corner point, found large stone and Set 3" x 24" Iron pipe, from which

A 12" W.Fir bears S.46°E., 42.2 ft. mkd. ¼ S32 BT.

A 6" Cedar bears N.10°E., 53.0 ft. mkd. ¼ S32 BT.

A cat road bears East, 35.0 ft. - it bears N.10°E., and S.10°W.

BLM resurvey by Wayne L. Rogers, under Group #1030, surveyed Aug/Sept. 1980 (DCSO records Vol. 45 Page(s) 17258)

The ¼ sec. cor., perpetuated and recorded by Markham in 1957, from which the remains of the original bearing tree

A Fir 15" dia., bears N.28°E., 39 lks. dist., with healed blaze.

and bearing trees mkd. by Markham

A Cedar 14" dia., bears N.10°E., 81 lks. dist., with healed blaze.

A sawed Fir stump 18" dia., bears S.46°E., 57 lks. dist., with illegible scribe marks visible on decayed blaze.

At the corner point

Set an iron post, 28 ins. long, 2 1/2 ins. dia., 24 ins. in the ground, with brass cap marked

T 29 S R 6 W
¼
S 31 | S 32
1980

from which a new bearing tree

A Fir 4" dia., bears N.79½°W., 35 lks. dist., mkd. X BT.

Fd. BC & 3 BTs by D. Edwards, 3/2011 - M162-22