

PRIMARY CORNER DESCRIPTION Sec. Cor. for 5, 6, 7 and 8

Alias	Description
Alias	Description
Alias	Description
Alias	Description

Original - Nathaniel Ford, under Contract #44 dated May 30, 1854 (DCSO records, Vol. 15 Page 6487)

Set post, cor. of secs. 5, 6, 7 and 8.
A W.Oak 20" dia., bears S.60°E., 275 lks. dist.
A Laurel 8" dia., bears N.87°E., 275 lks. dist.
A Red Fir 10" dia., bears S.53°W., 227 lks. dist.
No tree in reasonable dist. for sec. six.

G.G. Stewart, Deputy Co. Surveyor - For: Chas. Voytilla - Wit: Ed Walker; Geo. E. Keller; Chas Voytilla - Dec. 8, 1921 - C.S. File 34/13; C.S. File 6/18; Vol. 3 Pg. 96 (and "old" cor. book, Pg. 130)

Found two original BTs. Set at each tree and ran course and bearing as called for in notes. Points did not coincide so took the average of two for position of corner. Set iron pipe from which
A 36" Fir S.38°W., 28.6 ft.
A 6" Fir N.72°W., 15.0 ft.
A 4" W.Oak S.54½°E., 34.5 ft.
A 8" W.Oak N.10°E., 32.5 ft.

Cadastral survey by Hans W. Thielsen and C. Albert White under Group #s 348 and 350. Surveyed, July 23, 1958 to Aug. 5, 1959 (DCSO records Vol. 30 Page(s) 12838-39)

The Sec. cor., determined from bearing trees marked by Stewart in 1921. The Douglas County records show that Stewart recovered this cor. in 1921, from 2 orig. BTs and marked new bearing trees at that time.

At the corner point
Set an iron post, 28 ins. long, 2½ ins. dia., 22 ins. in the ground, with brass cap mkd: T 29 S R 6 W
 S 6 S 5
 S 7 S 8
 1958

from which the remains of trees marked by Stewart:
An Oak snag, 9" dia., bears N.10°E., 49 lks. dist., mkd. with portion of blaze.
An Oak 5" dia., bears S.54½°E., 52 lks. dist., mkd. with healed blaze.
A sawed Fir stump 36" dia., bears S.38°W., 43 lks. dist., mkd. with lower portion of healed blaze.
A fir 14" dia., bears N.72°W., 23 lks. dist., mkd. with illegible scribe marks on open blaze.

(Cont. Next Page)

PRIMARY CORNER DESCRIPTION Sec. Cor. for 5, 6, 7 and 8

Alias	Description
Alias	Description
Alias	Description
Alias	Description

and new bearing trees:
A Fir 13" dia., bears S.48½°E., 25 lks. dist., mkd. T29S R6W S8 BT.
A Fir 12" dia., bears S.28°W., 95 lks. dist., mkd. T29S R6W S7 BT.
A Fir 10" dia., bears N.33½°W., 28 lks. dist., mkd. T29S R6W S6 BT.
There is no suitable tree available in Sec. 5.

Corner Fd. and Used in BLM survey by Robert Chappell under Group #1616, surveyed June/Sept 1991 (DCSO records Vol. 30 Page(s) 18897-98) -
The corner is located alongside a woven wire fence, bears N.80°E. and S.80°W. and remains of fence bears N.

BLM Resurvey, by Dale B. Bedell, Surveyed under Group No. 1703. Surveyed Aug. 1993 thru May 1994. (D.C.S.O. records Vol. 52 Page(s)19676-77)

The cor. of secs. 5, 6, 7 and 8, is monumented with an iron post, 2 1/2 ins. diam., firmly set, projecting 8 ins. above the ground, with brass cap mkd.
S 6 S 5
S 7 S 8
T29S R6W
1958

from which the remains of bearing trees mkd. by Stewart, Deputy County Surveyor, in 1921.
A white oak, 10 ins. diam., bears S.54½°E., 50 lks. dist., with a healed blaze.
A sawed fir stump, 30 ins. diam., bears S.34°W., 43 lks. dist., with a rotted blaze.
A fir snag, 25 ins. diam., bears N.75°W., 23 lks. dist., with a healed blaze.
and the remains of bearing trees mkd. by Thielsen and White
A sawed fir stump, 22 ins. diam., bears S.48½°E., 24 lks. dist., with a healed blaze.
A decayed fir stump, size indeterminate, bears S.28°W., 95 lks., with reverse scribe mark T visible on overgrowth.
A fir, 17 ins. diam., bears N.33½°W., 28 lks. dist., with a healed blaze.
and a new bearing tree
A fir, 12 ins. diam., bears S.81½°W., 64 lks. dist., mkd. T29S R6W S7 BT.
No suitable bearing trees available NE. of corner.
The corner is located on a W. slope and in a wire fence line bearing N. 80° E. and S. 80° W.