

TOWNSHIP 29 RANGE 06 POINT IDENTIFIER # 300240

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 28 and 29

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO survey by H. G. Hurlburt, Deputy Surveyor, under Contract #285, dated June 20, 1878 (DCSO records Vol. 15 Page(s) 6494)

-----  
Set ¼ sec. post, from which  
    An Ash 8" dia., bears N.90°W., 34 lks. dist.  
    A Maple 10" dia., bears S.85°E., 21 lks. dist.

J. W. Cole, County Surveyor - Wit: M.B. Hawkins; Tog Rice - March 1924 - Vol. 3 Pg. 183-184; Field Book 90 Pg. 40 (and "old" corner book, pg. 132)

-----  
I found no evidence of the original corner but placed the corner on the true section line 1/2 way between section corners. The corner fell in creek on bed rock. I set an Iron pipe 1½" x 36" and erected mound of rock around pipe from which I marked:  
    Fir 48" dia., S.39°45'W., 20.5 ft.  
    Fir 48" dia., N.63°00'W., 39.7 ft.

Survey by Howard Johnstone - For: Roseburg Lumber Co. - June 1980 - M 84-10

-----  
Set 5/8" x 30" Iron rod and alum. cap.  
BTs - 8" Maple bears S.49°W., 39.4 ft.  
      24" Maple bears N.6°E., 54.9 ft.  
No evidence of corner set by County Surveyor in 1924. Set corner by standard subdivision procedure.