

TOWNSHIP 29 RANGE 06 POINT IDENTIFIER # 300300

PRIMARY CORNER DESCRIPTION Sec. Cor. for 20, 21, 28 and 29

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Original - Nathaniel Ford, under Contract #44 dated May 30, 1854 (DCSO records, Vol. 15 Page 6478)

Set post, cor. of secs. 20, 21, 28 and 29, from which
A B.Oak 12" dia., bears S.25°E., 34 lks. dist.
A B.Oak 14" dia., bears N.35°E., 10 lks. dist.
A B.Oak 6" dia., bears N.37°W., 35 lks. dist.
A B.Oak 8" dia., bears S.41°W., 25 lks. dist.

Corner found by H.G. Hurlburt, GLO survey, 1878 (DCSO records, Vol. 15 Pg. 6494)

Corner tied in GLO survey by Fred Mensch, 1904 (DCSO records, Vol. 15 Page 6514)

Jesse W. Cole, Surveyor - March 7, 1924 - Vol. 3 Pg. 183; Field Book 52 Pgs. 52-53

This corner has been renewed by some previous surveyor, and I noted the bearing of the new witness trees as follows:
A Fir 9" dia., S.88°E., 4.2 ft.
A Fir 12" dia., N.6°30'E., 4.2 ft.
A Fir 12" dia., S.38°30'W., 5.0 ft.
A Fir 12" dia., N.60°00'W., 31.5 ft.
I also set an Iron pipe 1¼" x 36" at the corner.
The remains of three of the original bearing trees could still be seen, but they were badly decayed.

Survey by J.H. Markham, Jr. - For Stomar Lumber Co. - March 21, 1951 - C.S. File 40/294

A 10" Fir stump bears East, 4.0 ft. scribed O.B.T. - C.S.
A 7" Fir bears N.62°W., 31.7 ft. scribed by C.S.
A Fir 14" dia., bears S.40°W., 4.5 ft. O.B.T. - C.S.
At corner point, found 1" pipe, from which
A Laurel 36" dia., bears S.60°W., 48.5 ft. marked S29 T29S R6W 2880 BT.

Douglas Co. Surveyors Office - James Byron, Deputy - Ray Irving; John Fee, crew - June 1954 - C.S. File 46/45-1(C&D)

Found - 1" Iron pipe on E-W fence line, Checks bearing and distance to
Laurel BT, 36", in good condition.
All other BTs in poor condition but check for bearings and distances.

(Cont. Next Page)

TOWNSHIP 29 RANGE 06 POINT IDENTIFIER # 300300

PRIMARY CORNER DESCRIPTION Sec. Cor. for 20, 21, 28 and 29

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Blazed and scribed:

14" R.Fir S.89°W., 5.5 ft. mkd. S29 T29S R6W CS BT
10" R.Fir S.38°E., 66.8 ft. mkd. S28 T29S R6W CSBT
18" R.Fir N.80°E., 100.0 ft. mkd. T29S R6W CS BT

Douglas Co. Surveyors Office - James Byron, Deputy - John Powell, Dale McFarland, crew - April 1962 - C.S. 49/139-39

Found - Pipe at corner.
15" R.Fir S.89°W., 5.5 ft. good condition.
NE BT is OK. Laurel to SW, now dead, and Fir to SE, now snag.
New BTs - (?) R.Fir bears S.42°E., 94.2 ft. scribed S28 T29S R6W CS BT.
9" R.Fir bears N.31°W., 6.5 ft. scribed S20 CS BT.

Fd OK, by Burt Holt, Oct. 1983, M 95-35

BLM Resurvey by Wayne L. Rogers and Bryan S. Seibold, Cadastral Surveyors, under Group #1517, surveyed April/Aug. 1990 - (DCSO records Vol. 50 Page(s) 19184)

The cor. of secs. 20, 21, 28, and 29, perpetuated and recorded by Cole, in 1924, from original evidence no longer in existence, further perpetuated and recorded by Markham, Jr., in 1951, and further perpetuated and recorded by Byron, in 1954 and 1962, monumented with an iron pipe, 1 in. diam., firmly set, projecting 3 ins. above ground, from which the remains of a bearing tree mkd. by Cole:

A sawed fir stump, 9 ins. diam., bears N. 60½° W., 48 lks. dist., no marks visible.

and the remains of the bearing trees mkd. by Byron in 1954

A sawed fir stump, 27 ins. diam., bears N. 80° E., 151½ lks. dist., with healed blaze.

A sawed fir stump, 11 ins. diam., bears S. 42° E., 112½ lks. dist., no marks visible.

A fir, 25 ins. diam., bears S. 88½° W., 8 lks. dist., with healed double blaze.

and the remains of the bearing trees mkd. by Byron in 1962

A sawed fir stump, 18 ins. diam, bears S. 42 3/4° E., 142½ lks. dist., with healed double blaze.

A fir, 23 ins. diam., bears N. 38 3/4° W., 9½ lks. dist., with healed double blaze.

At the corner point

Set a stainless steel post, 28 ins. long, 2½ ins. diam., 24 ins. in the ground, directly atop the iron pipe, with brass cap mkd.

(Cont. Next Page)

PRIMARY CORNER DESCRIPTION Sec Cor for 20, 21, 28 and 29

Alias	Description
_____	_____
_____	_____
_____	_____
_____	_____

<p>T 29 S R 6 W S 20 S 21 S 29 S 28 1990</p>
<p>from which new bearing trees A fir, 15 ins. diam., bears N. 21 3/4°E., 66 lks. dist., mkd. T29S R6W S21 BT. A fir, 14 ins. diam., bears S. 85½°E., 88½ lks. dist., mkd. T29S R6W S28 BT.</p>
<p>Douglas Co. Surveyors Office - Randall Smith, Stephen Flause - 6/20/1994 (before BLM resurvey filed) - C.S. File 64/52-5 ----- Found - 3¼" dia., BLM brass cap on a 2½" O.D. iron pipe protruding 4" above ground (1990 BLM pending resurvey) I.P. noted in renewals not visible All Orig. BTs and BTs from 1924 & 1951 now gone. From 1954 renewal 14" now 24" dia., 4 ft. high D.Fir stump with a fully healed double blaze, bears S.89°W., 5.5 ft. (agrees with rec) 18" now 24" dia., 2 ft. high D.fir stump with a fully healed lower blaze. We open and find good scribe marks "BT" bears N.81¼°E., 100.0 ft. (rec. N.80°E., 100.0 ft.) SE BT now gone BTs from 1962 renewal Unknown dia., 15" dia., ft high D.Fir stump with a fully healed single blaze bears S.43½°E., 94.2 ft. (rec. S.42°E., 94.2 ft.) 9" now 24" dia., 3½ ft. high D.Fir stump with a fully healed double blaze bears N.38¾°W., 6.5 ft. (rec. N.31°W., 6.5 ft.) BTs from 1990 (pending) resurvey (rec taken from BT tags) 20" dia., D.Fir with a partially healed single blaze illegible scribing visible, bears S.85½°E., 57.8 ft (rec. S.85½°E., 58.4 ft., dist. is to center of trunk.) 16" dia., 3 ft. high D.Fir stump with a partially healed single blaze, illegible scribing visible, bears N.21¾°E., 43.7 ft. (agrees with rec.) New BTs- 13" Dia., Madrone bark scribed "T29S R6W S29 CS BT", bears S.77¼°W., 34.0 ft. 13" dia., I.Cedar double blazed and scribed "T29S R6W S20 CS BT" bears N.28½°W., 47.7 ft. 4" dia., D.Fir double blazed and scribed "X BT" bears N.58½°E., 16.2 ft. Continued next page</p>

TOWNSHIP 29 RANGE 06 POINT IDENTIFIER # 300300

PRIMARY CORNER DESCRIPTION Sec. Cor. for 20, 21, 28 and 29

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Note - Corner lies near the intersection of a East-West and South running fence lines. 4½ ft. East of the intersection and 1½ ft. north of the East-West fence line. All brg's taken away from fence line. Declination 17¾°E

Fd. Ok by R. Quimby - 11/2008 - M157-4