

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 21 and 22

Alias	Description
_____	_____
_____	_____
_____	_____
_____	_____

<p>Original - Nathaniel Ford, under Contract #44 dated May 30, 1854 (DCSO records, Vol. 15 Pages 6474-75)</p> <p>-----</p> <p>Set ¼ sec. post, from which A B.Oak 14" dia., bears S.55°W., 5 lks. dist. A B.Oak 10" dia., bears S.43½°E., 23 lks. dist.</p>
<p>Ben B. Irving, Deputy Co. Surveyor - Wit: W.S. Crear; Chs. Lucas and Edward Evans - Jan. 26 & Feb. 1, 1929 - C.S. File 22/33; Vol. 3 Pg. 290 and M 6-1 (and "old" cor. bk. Pg. 193)</p> <p>-----</p> <p>Position identified by O.B.T., S.55°W., 5 lks. as described in original notes. BT now dead. Drove ¾" x 54" Galv. Iron pipe for corner and a 6" x 6" x 42" Cedar post scribed ¼ S. CS on Suth face; S21 on West face and S22 on East face. Marked new BTs A 14" Fir N. E., 14 lks. ¼ S22 CS BT. A 15" Fir S. W., 53 lks. ¼ S21 CS BT.</p>
<p>J.H. Markham, Eng. - Wit: Geo. & Wm. Vaughn - For: Stomar Lumber Co. - March 21, 1951 - C.S. File 40/294</p> <p>-----</p> <p>Completed notes. 16" Fir, N.73°E., 9.5 ft. dist. 20" Fir S.62°W., 34.0 ft. dist. At corner 7" x 7" Cedar post and ¾" iron pipe.</p>
<p>Douglas Co. Surveyors Office - John Powell and crew - Feb. 12, 1971 - C.S. File 49/139-141</p> <p>-----</p> <p>Found - Old scribed post, scribed "¼ S21 SCS". 16" now 16" D.Fir N.73°E., 9.5 ft. shows good scar. 20" now 22" D.Fir S.62°W., 34.0 ft. shows good scar After good search with metal finder, did not find iron pipe. Set Brass cap at cor. mkd: County Surveyors Office T 29 S R 6 W ¼ S 21 S 22 1971</p> <p>Bearing trees OK and tagged.</p>
<p>Douglas Co. Surveyors Office - R. B. Kimberling, Deputy - F.C. Silagy, crew - Jan. 4, 1978 - C.S. File 59/46-59</p> <p>-----</p> <p>Found - 1" I.P. with a 1971 DCSO brass cap set 14" above ground, properly marked. A 6" x 6" Cedar post is laying alongside brass cap with visible scribing "S C S" on one face. (Cont. Next Page)</p>

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 21 and 22

Alias	Description
_____	_____
_____	_____
_____	_____
_____	_____

14" now 15" Fir bears N.76°E., 9.8 ft. (Rec. N.73°, 9.5 ft.) with a well healed double blaze.
15" now 24" Fir stump is partly uprooted, orig. position approx. S.62°W., 34.0 ft. with visible reverse scribing "S21 CS" looking back from rotted center of stump.
New BT - 18" D.Fir bears S.3°W., 16.2 ft. with scribed "¼ S21 CS BT" in double blaze.
Corner is 35 ft. North of BLM road.

BLM Resurvey by Wayne L. Rogers and Bryan S. Seibold, Cadastral Surveyors, under Group #1517, surveyed April/Aug. 1990 - (DCSO records Vol. 50 Page(s) 19180)

The 1/4 sec. cor. perpetuated and recorded by Irving, Deputy County Surveyor, in 1929, from original evidence no longer in existence, further perpetuated and recorded by Powell, Deputy County Surveyor, in 1971, and further perpetuated and recorded Kimberling, Deputy County Surveyor, in 1978, monumented with an iron post, 1¼ ins. diam., firmly set, projecting 10 ins. above ground, with mkd. brass cap. from which the remains of the bearing trees mkd. by Irving

- A sawed fir stump, 18 ins. diam., bears N. 77¼° E., 14½ lks. dist., with healed blaze.
- A sawed fir stump, 24 ins. diam., bears S. 59 3/4° W., 53½ lks. dist., with fragmentary scribe marks in reverse and relief visible on decaying stump.

and the remains of a bearing tree mkd. by Kimberling

- A fir snag, 28 ins. diam., bears S. 2 3/4° W., 25 lks. dist., with fragmentary scribe marks visible on partially healed blaze.

and new bearing trees

- A fir, 22 ins. diam., bears S. 44½° E., 21½ lks. dist., mkd. 1/4 S22 BT.
- A fir, 10 ins. diam., bears S. 77¼° W., 39 lks. dist., mkd. 1/4 S21 BT.

From this point, the Bureau of Land Management Geodetic Control Station No. EC41047, at latitude 43° 01' 33.107" N., longitude 123° 23' 54.293" W. (NAD 1927), determined by the NAVSTAR Global Positioning System, bears S. 21° 54' 36" E., 52.739 chs. dist. (mean bearing and sea level distance), monumented with an aluminum cap, firmly set flush in concrete, with top mkd. GPS EC41047 1990.

continued next page

2

TOWNSHIP 29 RANGE 06 POINT IDENTIFIER # 400340

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 21 and 22

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

BLM dependent resurvey by Jeffrey O. Covington, Cadastral Surveyor, under Group No. 2940, surveyed June/Sept. 2019- (DCSO records Vol. 59 Page(s) 24021-2)

The ¼ sec. cor. of secs. 21 and 22, reported by Rogers and Seibold in 1990, monumented with an iron post, 1¼" dia., firmly set, projecting 9" above ground, with a brass cap (properly) mkd.

from which the remains of the bearing trees reported by Rogers and Seibold

A decayed fir stump, 16" dia., bears N.77¼°E., 9.6 ft., with a healed blaze.

A fir, 26" dia., bears S.44½°E., 14.2 ft., with a healed blaze.

A decayed fir stump, 28" dia., bears S.2¾°W., 16.5 ft., with scribe marks BT visible on open blaze.

A decayed fir stump, 30" dia., bears S.59¾°W., 35.3 ft., with illegible reverse scribe marks visible on open blaze.

A fir, 17" dia., bears S.77¼°W., 25.7 ft., with a healed blaze.

Corner is located N., 80 ft., of graveled road, 14 ft. wide, bears S.80°E. and N.70°W.