

TOWNSHIP 29 RANGE 06 POINT IDENTIFIER # 440300

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 22 and 27

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Original - Nathaniel Ford, under Contract #44 dated May 30, 1854 (DCSO records, Vol. 15 Page 6474)

-----  
Set ¼ sec. post, from which  
A B.Oak 12" dia., bears N.63°W., 63 lks. dist.  
A B.Oak 18" dia., bears S.37°E., 84 lks. dist.

Survey by John H. Markham, Jr. - For: Stomar Lumber Company  
-Wit: Wm. & Geo. Vaughn - Dec. 1950 - C.S. File 40/294

-----  
Set at proportional distance.  
At corner point, Set 1" x 30" I.P., 15" in ground from which  
A Fir 36" dia., bears S.36°W., 18.0 ft. marked ¼ S S27  
2880 BT.  
A Myrtlewood 8" dia., bears N.37°E., 44.0 ft. marked ¼ S  
S22 2880 BT.

Cadastral survey by Hans W. Thielsen and C. Albert White  
under Group #s 348 and 350. Surveyed, July 23, 1958 to Aug.  
5, 1959 (DCSO records Vol. 30 Page(s) 12821)

-----  
Point for the ¼ sec. cor., at proportionate distance; there  
is no remaining evidence of the original corner.  
Set an iron post, 28 ins. long, 2½ ins. dia., 20 ins. in the  
ground, with brass cap mkd: ¼  $\frac{S\ 22}{S\ 27}$   
T 29 S R 6 W  
1958

from which  
A Fir 11" dia., bears N.18°W., 59 lks. dist., mkd. ¼ S22  
BT.  
A Fir 38" dia., bears S.23°W., 30 lks. dist., mkd. ¼ S27  
BT.

BLM resurvey by Wayne L. Rogers and Bryan S. Seibold,  
Cadastral Surveyors, under Group #1517, surveyed April/Aug.  
1990 - (DCSO records Vol. 50 Page(s) 19178-79)

-----  
The 1/4 sec. cor. monumented with an iron post, 2½ ins.  
diam., firmly set, projecting 9 ins. above ground, with brass  
cap mkd. S 22  
1/4 \_\_\_\_\_  
S 27  
T 29 S R 6 W  
1958

from which the remains of the bearing trees mkd. by Thielsen  
and White  
(Cont. Next Page)

TOWNSHIP 29 RANGE 06 POINT IDENTIFIER # 440300

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 22 and 27

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

A fir snag, 36 ins. diam., bears S. 23° W., 30 lks. dist., mkd. 1/4 S27 BT on the bark.  
A fir, 19 ins. diam., bears N. 18° W., 59 lks. dist., with healed blaze.  
and a new bearing tree  
A fir, 6 ins. diam., bears S. 18¼° E., 61½ lks. dist., mkd. 1/4 S27 BT.  
The corner is located in a woven wire fence line extending E. and W.

BLM dependent resurvey by Jeffrey O. Covington, Cadastral Surveyor, under Group No. 2940, surveyed June/Sept. 2019- (DCSO records Vol. 59 Page(s) 24018-9)

-----

The ¼ sec. cor. of secs. 22 and 27, reported by Rogers and Seibold in 1990, monumented with an iron post, 2½" dia., firmly set, projecting 8" above ground, with a brass cap (properly) mkd.  
from which the remains of the bearing trees reported by Rogers and Seibold  
A fir, 22" dia., bears S.18¼°E., 40.6 ft., with a healed blaze.  
A decayed fir stump, 36" dia., bears S.23°W., 19.8 ft., no marks visible.  
A fir, 26" dia., bears N.18°W., 38.9 ft., with a healed blaze.

From this cor., a point erroneously established as the ¼ sec. cor. of secs. 22 and 27, by Markham Jr., in 1950. This point was not correctly positioned and was not utilized for control in this survey, bears N.68°16'42"E., 4.23 ft.; as determined at record bearing and from a bearing tree mkd. by Markham Jr.  
A myrtle, 19" dia., bears N.37°E., 44.0 ft., with a healed blaze.